

#### COVID-19 Update

To support safe SaskSurplus Sale operations during the COVID-19 pandemic, new measures have been introduced for clients to follow. These include online-only viewings of sale items, a pre-pickup screening checklist, and SaskSurplus Sales - Pick-up Guidelines.

The safety of SaskSurplus clients and employees is our top priority, and we thank you for your cooperation with these new measures. For general Government of Saskatchewan information related to COVID-19, please visit [saskatchewan.ca](http://saskatchewan.ca)

Every effort has been made to accurately describe items and their condition; however additional problems may exist, items may not be complete or exactly as described. Bidders are deemed to have reviewed the Terms and Conditions on bid forms and relied entirely on their own inspection and evaluation prior to bidding. Vehicles and equipment are sold "AS IS, WHERE IS", there is no implied or express warranty.

Visit [www.SaskSurplus.ca](http://www.SaskSurplus.ca) for pictures and link to download Bid Form.

- Items identified with \* have been on a previous sale and will be listed first on [www.SaskSurplus.ca](http://www.SaskSurplus.ca) web site.
- Central Services, SaskSurplus reserves right to have unadvertised minimum selling prices on items.

It is the Bidder's responsibility to review the terms and conditions of sale on the Offer to Purchase, Bid Form.

Bid Forms are available from [www.SaskSurplus.ca](http://www.SaskSurplus.ca) or from the SaskSurplus Sales Lot, 500 McLeod Street, Regina, SK.

Bid Forms can be submitted in the following ways:

- by deposit in the bid box at the SaskSurplus Sales Lot.
- by fax to (306)787-2092; by phone (306)787-2062 or (306)787-2238
- by email to [sasksurplus@gov.sk.ca](mailto:sasksurplus@gov.sk.ca)
- or by mail, addressed to: Ministry of Central Services, SaskSurplus, 500 McLeod Street, Regina, SK S4N 4Y1.  
(If mailing your bid, please allow sufficient time for bid to be received.)
- Bids received after close date and time cannot be accepted.

MT = (Ministry Transfer) This means that the item has been claimed by another ministry and automatically transferred.

WD = (Withdrawn) This can happen if the item was requested to be removed by the seller,  
or if bid prices did not meet the seller's minimum selling price. In this case, the item may be carried forward to a future sale.

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>REGINA, Central Services, SaskSurplus Sales Lot, 500 McLeod Street - Vehicles</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact SaskSurplus (306) 787-2062 or (306) 798-3306</b>						
<b>861.61 X-037</b>	Car 2006 CHEVROLET Cobalt LS 4 Door 2.2L L4 gas auto air, cruise, tilt, AM/FM/CD player, PL , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both inner tie rods, front rotors, park brake not holding/cable pass rear unhooked, plate light, hood rust/dents/chips/scratches, both bumpers chips/scratches, both right fenders small dents, right front door small dents, trunk lid dents, windshield cracked, parking lots dents & scratches>, As is, Where is	278,366 Kms	1G1AJ55F567845141	CVA	118166 TOW ONLY, 54-7	2002-1119
<b>2,727.98 * 12-022</b>	Car 2008 CHEVROLET Impala LS 4 door 3.5L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PW, PM, power trunk release, power driver seat, heated mirrors , Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left front head light, tire light, front pads & rotors, hood chips/scratches, rear right bumper chips/scratches, left front fender scratches, both rocker panels road rash, trunk lid scratches, windshield chips, parking lots dents & scratches>, As is, Where is	228,656 Kms	2G1WB58K081357288	CVA	316190 TOW ONLY, 120-3	2001-1070
<b>WD 1,003.21 X-024</b>	Car 2009 CHEVROLET Impala LS 4 door 3.5L V6 gas auto dual zone air, tilt, cruise, AM/FM/CD player, PL, PW, PM, power trunk release, power driver seat , Blue, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right front ball joint loose, left front control arm bushing/worn, right washer nozzle, wiper blades worn, hood chips/scratches/dents, both bumpers chips/scratches/road rash, both rear fenders rust/scratches, all doors scratches/rust along the bottom, roof rust on edges, trunk lid scratches/dents, windshield chips, parking lot dents & scratches>, As is, Where is	309,337 Kms	2G1WB57K491124873	CVA	316489 TOW ONLY, 122-4	2004-029

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>WD 1,953.00 X-028</b>	Car 2013 CHEVROLET Impala LS 4 door 3.6L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PM, PW, power driver seat, power trunk release , Grey , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , PROBLEMS: rear links, both rear valve stems leaking, grille broken, hood chips/dents/scratches, both bumpers chips/scratches, left front fenders scratches, driver door rust at bottom, roof scratches/rust spots, trunk lid scratches, windshield chips, driver seat worn, parking lot dents & scratches>, As is, Where is	277,953	2G1WA5E35D1256693	CVA	800058 TOW	2004-026 ONLY, 122-7
<b>1,222.22 X-048</b>	Car 2007 CHEVROLET Impala LS 4 Door 3.5L V6 gas auto air, tilt, cruise, AM/FM/CD player, PW, PL, PM, power driver seat, power trunk release, heated mirrors , Brown , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , PROBLEMS: SES & engine light on, engine lacking power, rusted rotors, PS rack leaking, PS pressure hose leaking, PS fluid low, brake noise, engine oil leaking from intake, hood chips/scratches/dents, both bumper chips/scratches, both rockers road rash, all doors road rash/rusting, trunk lid scratches, windshield chips/scratches, right front seat stained, parking lot dents & scratches> , As is, Where is	231,639	2G1WB58KX79388337	CVA	313643 TOW	2002-1132 ONLY, 52-7
<b>579.00 X-073</b>	Car 2004 CHRYSLER Intrepid SE 4 door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release , Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , PROBLEMS: huge oil leak, hood shocks, floor rusted, driver rear window won't roll down, hood chips/dents, both bumpers chips/scratches/paint poor, all 4 fenders chips/ scratches/dents, driver door rusted, trunk lid rusted, windshield chip, parking lots dents & scratches> , As is, Where is	288,879	2C3HH46R74H598392	CVA	311902 TOW	2001-1117 ONLY, 103-2

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,651.12 * 12-015	Car 2008 CHRYSLER Sebring TOURING 4 door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PW, PM, power trunk release, heated mirrors , Beige , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, rear pads, hood chips/scratches/dents, both bumpers chips/scratches, left front fender chips/scuffs, both rocker panels road rash, all 4 doors dents/road rash, roof dents, trunk lid scratches/dents, windshield chips, sun visor clip is broken, parking lots dents & scratches>, As is, Where is	259,048 Kms	1C3LC56RX8N230526	CVA	156125 TOW	2001-1063 ONLY, 105-5
827.12 X-068	Car 2009 CHRYSLER Sebring LX 4 door 2.4L L4 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release, heated mirrors , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both front lower ball joints loose, trans cooler lines leaking, left rocker molding loose, hood paint bubbling/dents/scratches, both bumpers chips/scratches/cracked/rusted, left front fender scratches, right rear inner fender liner broken, all 4 doors rusted, trunk lid scratches/rusted, right mirror wrong color, wheel alignment out of spec, windshield chips, rear window headliner loose, parking lots dents & scratches>, As is, Where is	281,644 Kms	1C3LC46B49N573413	CVA	157818 TOW	2001-1112 ONLY, 103-7
WD 827.12 X-022	Car 2009 CHRYSLER Sebring LX 4 Door 2.4L L4 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, power trunk release, heated mirrors , Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: all 4 rotors rusted, rear shock leak, right rear lamp broken, both head lamps hazed over, brake noise, hood chips/dents/scratches/paint bubbling, both bumpers chips/scratches, all fenders scratches/dents/rust, rockers road rash, all doors scratches/road rash, roof dents, trunk lid scratches/rust/dents windshield cracked, headliner loose, left rear tail light lense broken, wheel alignment, parking lot dents & scratches> , As is, Where is	286,580 Kms	1C3LC46B59N573436	CVA	158329 TOW	2002-1159 ONLY, 115-8

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
732.51 X-029	Car 2006 CHRYSLER Sebring Touring 4 door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM, keyless entry- 2 fobs , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: park brake not holding, rack/pinion leaking, trans cooler lines leaking, wheel alignment, driver's sun visor broken, power locks don't work on driver door, hood scratches, both bumpers chips/scratches, right rear fender rusted, left rear door rusted at bottom inside, trunk lid scratches & dents, wiper blades, parking lot dents & scratches>, As is, Where is	236,625 Kms	1C3EL56R06N223655	CVA	140301 TOW ONLY, 118-4	2004-016
1,543.21 X-069	Car 2006 CHRYSLER Sebring Touring 4 door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release, keyless entry-2 fobs & 2 keys , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: all 4 rotors corroded, brake & tire vibration, hood chips/scratches, both bumpers chips/scratches, LF & RR fenders scratches/rusted, right rocker rusted, roof paint faded/rusted, windshield chips, wheel alignment, parking lots dents & scratches>, As is, Where is	139,894 Kms	1C3EL56R66N223711	CVA	140624 TOW ONLY, 103-6	2001-1113
1,177.12 X-015	Car 2006 CHRYSLER Sebring Touring 4 Door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PW, PL, PM, power trunk release , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: battery tested bad, rear rotors rusted, rear license plate lamps inoperative, head lamps hazed over, tire brake noises, wheel alignment, hood chips/scratches, both bumpers chips/scratches, all fenders chips/scratches/rust, both left doors rust/chips, roof dents, windshield chips, parking lot dents & scratches>, As is, Where is	229,392 Kms	1C3EL56R26N223687	CVA	140939 TOW ONLY, 117-7	2002-1152

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,100.31 X-030	Car 2006 CHRYSLER Sebring Touring 4 door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player after market, PL, PM, PW , Silver , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, P0420 catalyst bank 1 efficiency, steering rack/pinion leaking, front struts leaking, passenger sun visor clip, wiper blades, hood scratches & chips, both bumper chips & scratches, left front fender scratches, right rocker paint peeling, windshield chips, parking lot dents & scratches>, As is, Where is	191,288 Kms	1C3EL56RX6N223677	CVA	141283 TOW ONLY, 118-3	2004-017
990.00 X-071	Car 2006 CHRYSLER Sebring Touring 4 door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release , White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left rocker rusted, front links, oil pan gasket sweating, hood chips/scratches, both bumpers damaged and loose, both left fenders scuffed/rusted, left rocker rusted, left rear door dents, roof dents, trunk lid scratches/dents, windshield chips, parking lots dents & scratches>, As is, Where is	183,903 Kms	1C3EL56R86N223693	CVA	141788 TOW ONLY, 103-4	2001-1115
861.61 X-014	Car 2007 CHRYSLER Sebring Touring 4 Door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PW, PL, power trunk release, power driver seat, heated mirror , Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: transmission leak, tires worn out, rear struts, shifter stiff, steering column rubbing, hood dents/paint bubbling, both bumpers chips/scratches, all fenders scratches/scrapes/rust, all doors scratches/scrapes/rust, roof dents, trunk lid dents, windshield chips, right front seat stained, parking lot dents & scratches>, As is, Where is	248,411 Kms	1C3LC56R17N634801	CVA	142752 TOW ONLY, 117-8	2002-1151

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,051.99 X-059	Car 2007 CHRYSLER Sebring TOURING 4 Door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM, power driver seat, heated mirrors, keyless entry-2 fobs , Gold, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, misfire needs coil, right lower ball joint, rear struts, front links, brake rotors rusted, hood chips/scratches/paint bubbling, front bumper cracked/chips/scratches, both rear fenders rusted, left rocker rusted, right front door dents, roof dents, trunk lid scratches/dents, windshield chips, parking lot dents & scratches>, As is, Where is	193,972 Kms	1C3LC56R37N634704	CVA	148544 TOW	2002-1180 ONLY, 112-2
1,027.12 X-008	Car 2007 CHRYSLER Sebring TOURING 4 door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release, power driver seat, heated mirrors , Gold , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, front strut mounts, front sway bar links, front brake rotors, rear park shoes/hardware, gas cap error message, hood paint bubbling/dents/scratches, both bumpers cracked/chips/scratches, both left fenders rusted/scratched, both rockers road rash, all 4 doors rusted/road rash, roof hail, right roof rail dented, headliner loose at back, trunk lid hail dents/scratches, windshield chips, right front seat stained, front alignment, parking lots dents & scratches>, As is, Where is	221,308 Kms	1C3LC56R97N634707	CVA	150326 TOW	2001-1106 ONLY, 104-6
923.00 X-049	Car 2007 CHRYSLER Sebring Touring 4 Door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PW, PL, PM, power driver seat, power trunk release, heated mirrors , Red , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, engine light on, P0562 system voltage low, right front fender reflector, wheel alignment, missing spare tire, hood paint bubbling/scratches/dents, both bumpers chips/scratches/cracked, right rear fender rusted, both rockers rusted, all doors road rash, roof dents, trunk lid scratches/dents, windshield cracked, parking lots dents & scratches>, As is, Where is	243,923 Kms	1C3LC56R87N634732	CVA	146894 TOW	2002-1133 ONLY, 52-6

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
757.00 X-039	Car 2007 CHRYSLER Sebring Touring 4 Door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release, power driver seat, heated mirrors , Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , RECENT REPAIRS: both front windows are operating normally , PROBLEMS: no blower motor (heater), rear strut mounts, missing hub cap, hood paint bubbling/chips/scratches, both bumpers cracked/chips/scratches, both left fenders scratches/rust, both rockers rust/road rash, right rear door rust/road rash, roof rusted/scratches/dented, trunk lid scratches, windshield chips, head liner above rear window falling off, parking lots dents & scratches>, As is, Where is	241,757 Kms	1C3LC56R37N640180	CVA	156463 TOW	2002-1121 ONLY, 54-5
2,077.12 X-060	Car 2008 CHRYSLER Sebring TOURING 4 Door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM, heated mirrors, power trunk release , Beige , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left lower ball joint, rear toe links, front brake rotors, wheel alignment, hood scratches/paint bubbling, both bumpers chips/scratches/marks, LF & RR fenders rust, trunk lid small dents, windshield chips, parking lot dents & scratches >, As is, Where is	146,634 Kms	1C3LC56R58N230529	CVA	156307 TOW	2002-1181 ONLY, 112-1
1,127.12 X-002	Car 2008 CHRYSLER Sebring Touring 4 door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PW, PM, power trunk release, heated mirrors , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right lower ball joint, drivers rear valve stem, rear rotors, windshield top molding/chips, hood scratches/paint bubbling, both bumpers chips/scratches/front cracked, all 4 fenders dents/scratches/rusted, both rockers road rash, all 4 doors road rash/rusted, roof dents/rust , trunk lid dents, right visor clip broken, parking lots dents & scratches>, As is, Where is	253,032 Kms	1C3LC56R08N230437	CVA	157362 TOW	2001-1081 ONLY, 108-6



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
875.32 X-031	Car 2006 CHRYSLER Sebring Touring 4 door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM, power trunk release , Gold, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEM: rocker panels rusted, wheel alignment, hood small chips/scratches/hail, both bumper small chips, left front fender scratches, both rear doors starting to rust, roof hail dents, trunk lid hail dents, windshield chips, parking lot dents & scratches>, As is, Where is	196,472 Kms	1C3EL56R86N223676	CVA	140988 TOW ONLY, 122-5	2004-028
2,377.12 X-038	Car 2007 CHRYSLER Sebring Touring 4 Door 2.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power trunk release, power driver seat, heated mirrors , Gold, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: battery failed, both rear tires poor/worn out, SES and TPMS light on, high mount stop lamp inoperative, wheel alignment of out spec, hood paint bubbling/scratches, both bumpers scratches/chips, both left fenders dents, both left doors dents in window moldings/rust along bottom, trunk lid scratches/dents, windshield cracked, parking lots dents & scratches> , As is, Where is	113,589 Kms	1C3LC56R47N634694	CVA	144816 TOW ONLY, 54-6	2002-1120
1,477.12 X-023	Car 2008 CHRYSLER Sebring TOURING 4 Door 2.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, power trunk release, heated mirrors , Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: needs battery, all 4 rotors rusted, both rear shocks leaking, right front strut leaked out, wheel alignment, engine oil pan leaking, brake pulsation, head lamps hazed over, both bumpers scratches/chips, right rocker dents, roof dents, trunk lid scratches/dents, windshield chips, right mirror housing scratches, left rear carpet stained, head liner loose at back, parking lot dents & scratches>, As is, Where is	190,203 Kms	1C3LC56R58N230451	CVA	157065 TOW ONLY, 115-7	2002-1160

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,368.00 X-075	Car 2011 DODGE Avenger SXT 4 door 2.4L V4 gas auto air, tilt, cruise, AM/FM/CD player PL, PM, PW, power trunk release , Black, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right lower ball joint, right outer tie rod, front rotors, rear rotors, drive belt, hood chips/scratches, both bumpers chips/scratches, all fenders rust/scratches/road rash, both rockers road rash, both left doors chips/road rash, trunk lid scratches, windshield cracked, wheel alignment, parking lot dents & scratches>, As is, Where is	304,368 Kms	1B3BD4FB5BN501227	CVA	158204 TOW ONLY, 120-6	2004-020
3,733.99 X-040	SUV 2009 CHEVROLET Suburban 1500 LS 4WD, 6 passenger 5.3L V8 gas auto front air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power driver seat, rear HVAC front tow hooks, grille inserts, roof rails, cargo barrier, side steps, hitch, trailer wiring, right rear 1/4 glass defogger, Gold , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: battery failed test, transmission cooler leaking, oil pan leak, both brake rotors rusted, right rear inner fender liner broken, right front inner fender liner mounting, both rear mud flaps mounting, front wheel alignment, hood dents/scratches, both bumpers dents/road rash, all 4 fenders dents/scrapes/road rash, roof dents/scratches/rusted, tailgate rusted/glass scratched, wheel wrench & jack missing, windshield chips, left mirror housing broken, parking lots dents & scratches>, As is, Where is	244,140 Kms	1GNFK16309R272284	CVA	437092 TOW ONLY, 54-4	2002-1122

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>3,111.11 X-003</b>	SUV 2009 FORD Escape XLT 4WD, 5 passenger 3.0L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PW, PM, power driver seat, heated mirrors, keyless entry-2 fobs grille inserts, roof rack, hitch, 4 prong plug in, Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front links, hood chips/scratches/dents, both bumpers chips/scratches/ rear bumper skin loose, all 4 fenders scratches/rusted, both rockers panel rusted out, both left doors road rash, roof scratches, tailgate badly rusted/ skin separated from front tailgate, wheel wrench & jack located in right rear compartment, windshield cracked, parking lots dents & scratches>, As is, Where is	137,579 Kms	1FMCU93G39KC55723	CVA	442905 TOW	2001-1082 ONLY, 108-5
<b>1,751.51 * 11-017</b>	SUV 2006 FORD Explorer XLT 4WD, 4 door 4.0L V6 gas auto air, cruise, tilt, AM/FM/CD/MP3 player, PL, PW, PM, power driver seat, heated mirrors, keyless entry hitch, roof rack, note pad stand, Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both front struts leaking, front brake rotors pulsating, grille chrome peeling, hood chips/dents/trim loose, both bumpers chips, both rocker panels rusted through pass weather strip, right rear door handle, roof dents, windshield chips, parking lots dent & scratches> , As is, Where is	244,796 Kms	1FMEU73E16UB26441	CVA	439422 TOW	2001-1023 ONLY, 118-3
<b>WD 1,517.00 X-076</b>	SUV 2008 JEEP Commander Sport 4WD, 7 passenger 3.7L V6 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM, heated mirrors, power driver seat grille inserts, driving lights, roof rails, hitch, trailer wiring, , Green, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, exhaust leak, DF front axle outer boot ripped, rear rotors rusty, both valves covers leaking, head gasket leaking, wheel alignment, hood chips/scratches, both bumpers cracked/chips/scratches, all fenders chips/scratches, spare tire missing, windshield chips, left rear wheel flare cracked/scratched/road rash, right front wheel flare scratched, left roof rail paint poor, seats soiled, parking lot dents & scratches>, As is, Where is	244,517 Kms	1J8HG48KX8C225170	CVA	433216 TOW	2004-031 ONLY, 122-2

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,920.00 X-051	SUV 2007 JEEP Commander Sport 4WD, 7 passenger 3.7L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, power driver seat, driving lights roof rack with rails, Green, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , RECENT REPAIRS: 3 rear lug nuts, tire light , PROBLEMS: rear wiper arm broken, grille broken, hood chips/scratches, both bumpers chips/scratches/rear pad cracked, all fenders chips/scratches, all doors road rash, roof rust spots, tailgate chips, windshield cracked, front wheel flares chips/scratches, parking lots & scratches>, As is, Where is	245,920 Kms	1J8HG48K47C659454	CVA	432242 TOW	2002-1135 ONLY, 52-4
880.00 X-056	SUV 2008 SATURN VUE GREEN LINE HYBRID 2WD, 5 passenger 2.4L L4 gas auto air, tilt, cruise, PL, PM, PW, keyless entry -2 fobs , White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , RECENT REPAIRS: anti-lock brakes, indicator lamps , PROBLEMS: Engine poor, SES light on, missing compressor & tire repair kit, service traction control light on, head gasket leaking into motor, rough idle, grille dents, hood chips, front bumper chips/scratches, tailgate rusting/lifts are weak, full size spare tire, missing wheel wrench & jack, windshield chips, parking lot dents & scratches>, As is, Where is	180,034 Kms	3GSCL93Z08S590924	CVA	403550 TOW	2002-1177 ONLY, 112-5

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
3,827.12 X-064	Truck 2014 CHEVROLET Silverado 1500 4WD, crew cab, has back seat, 5'10" box 4.3L V6 gas auto air, tilt, cruise, AM/FM radio PL, PM, PW, power driver seat, keyless entry -2 fobs grille inserts, front tow hooks, rear mud flaps, headache rack, beacon, hitch, trailer wiring, OEM trailer brake, tuxedo rollup tonneau cover- condition unknown, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, both inner tie rods, exhaust manifold leaking, front tires, front differential pinion seal leaking, mud flaps missing, plate light & high mount light, hood chips/scratches, both bumpers chips/scratches, all 4 fenders chips/dents/scratches/rust/road rash, all doors paint chipping/rusted/bottom latch inoperable, roof rust stain, tailgate dents/scratches, windshield chips, driver cushion worn, driver back seat panel loose, parking lot dents & scratches>, As is, Where is	325,362 Kms	3GCUKPEH9EG379327	CVA	800238 TOW	2002-1185 ONLY, 111-4
2,052.12 X-034	Truck 2003 CHEVROLET Silverado 2500HD 4WD, reg cab, 8' box 6.0L V8 gas auto dual zone air, tilt, cruise, AM/FM radio hitch, trailer wiring, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , RECENT REPAIRS: accelerator pedal, indicator lamps, PROBLEMS: floor rusted/hole under driver seat, door pins & stops both doors, body mounts all moving, exhaust leak from muffler, front seats holes in cushion/frame visible/adjustment lever missing, tire vibration, bumpers dents/rear pads loose/ trim cut, both left fenders rust/dents, both front doors dents/2 holes on left side, tailgate dents, spare tire loose in box- may not be compatible with vehicle, wheel wrench & jack loose behind seat, both box rails dented, cab dents above box, head liner loose, cluster not working, cab corners rusted, wheel alignment, parking lot dents & scratches> , As is, Where is	186,835 Kms	1GCHK24U33E147071	CVA	434944 TOW	2002-1171 ONLY, 114-3

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,827.12 X-004	Truck 2005 CHEVROLET Silverado 2500HD 4WD, ext cab, has a back seat, 8' box 6.0L V8 gas auto dual zone air, cruise, tilt, AM/FM radio, PL front tow hooks, mud flaps, hitch, trailer wiring, electric trailer brake, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear pads & rotors, rear caliper pins sticking, both cab corners & rockers rusted through, drivers door pins slight play, left lower ball joint slight play, hood chips/scratches/dents, both bumpers dents/bent, all 4 fenders dents/rusted, both rockers rusted, right rear door dents, roof scratches/dents/rust spots/3 holes sealed, tailgate dents/scratches/paint chips, driver seat hole, lid for jump seat missing, driver visor worn, parking lots dents & scratches>, As is, Where is	303,911 Kms	1GCHK29U95E281952	CVA	437475 TOW ONLY, 108-4	2001-1083
2,627.12 X-006	Truck 2006 CHEVROLET Silverado 2500HD 4WD, ext cab, has back seat, 8' box 6.0L V8 gas auto dual zone air, cruise, tilt, AM/FM radio front tow hooks, mud flaps, antenna on left front fender, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: transmission pan gasket leaking, battery marginal, left inner tie rod, front links, both front door pins need adjusting, front bumper out of line/damaged, cab corners rusted, rear bumper pads loose/dents, roof 4 holes sealed, tailgate chips/dents/scratches, spare tire loose in box-may not be compatible with vehicle, windshield chips, front box cracked/behind cab dents/bent, missing wheel chocks, minor cosmetic damages, parking lots dents & scratches>, As is, Where is	308,293 Kms	1GCHK29UX6E270430	CVA	438093 TOW ONLY, 108-2	2001-1085

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>2,627.12 X-007</b>	Truck 2006 DODGE Ram 1500 4WD, quad cab, has back seat, 6'3" box 5.7L V8 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW, heated mirrors front tow hooks, grille inserts, side steps, hitch, trailer wiring, mud flaps, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, front sway bar bushing, driver mirror cracked, oil level dark, hood chips, all 4 fenders dented/rusted, all doors dented/rusted, roof 3 holes sealed, tailgate chips/dents/rusted, hole in seat, wheel wells in box badly dented, holes in dash, parking lots dents & scratches>, As is, Where is	287,130 Kms	1D7HU18236J228263	CVA	439380 TOW	2001-1086 ONLY, 108-1
<b>2,777.12 * 12-007</b>	Truck 2007 DODGE Ram 2500 RWD, quad cab, has back seat, 8' box 5.7L V8 gas auto air, cruise, tilt, AM/FM/CD player, PL, PW, PM headache rack, beacon, electric trailer brake, trailer wiring, hitch, hood deflector, side steps, computer stand, rear mud flaps, Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, lower ball joints loose, tail lamp broken, high mount stop lamp out, both rear brake rotors rusted, driver seat cover & cushion, all 4 fenders rusted/not secure, grille broken, hood chips/dents/scratches, front bumper bent/pad broken, tailgate dents/scratches/bent, windshield cracked, windshield wipers, front alignment, parking lots dents & scratches>, As is, Where is	287,297 Kms	3D7KR28D37G815791	CVA	450338 TOW	2001-1055 ONLY, 106-1
<b>3,377.12 * 12-010</b>	Truck 2008 DODGE Ram 2500 4WD, quad cab, has back seat, 6'2" box 5.7L V8 gas auto air, cruise, tilt, AM/FM/CD player grille inserts, front tow hooks, side steps, mud flaps, hitch, trailer wiring, roll up tonneau cover, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: parking brake hardware, parking brake shoes, grille broken, hood chips, both bumpers dents/scratches/rusted, all 4 fenders dents/road rash/rusted, roof rust spots, tailgate dents/rusted, windshield cracked, driver seat hole, parking lots dents & scratches>, As is, Where is	279,089 Kms	3D7KS28D78G226880	CVA	432440 TOW	2001-1058 ONLY, 49-3

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
2,127.27 X-019	Truck 2007 DODGE Ram 2500 RWD, quad cab, has back seat, 6'3" box 5.7L V8 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, heated mirrors grille inserts, side steps, mud flaps, hitch, trailer wiring, brake control, headache rack, beacon, arrow board with control- condition unknown, Silver, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, rear brake pads worn, rear brake rotors corroded, battery leaking, driver seat cushion torn/metal exposed, exhaust pipe broken before muffler, driver belt damaged, front lower control arm bushing, plate bulb out, mud flaps not secure, front right fender corroded/not holding liner, right rear fender rust/dents/scratches/paint poor, holes in front bumper pad, holes in bed box, windshield chips, minor cosmetic damages, parking lot dents & scratches>, As is, Where is	277,215 Kms	3D7KR28D17G811206	CVA	450577 TOW	2002-1156 ONLY, 117-3
3,977.12 * 11-039	Truck 2012 DODGE RAM 2500HD 4x4, crew cab has back seat, 6'3" box 5.7L V8 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM, heated mirrors grill inserts, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, soft tonneau cover, headache rack with 2 beacons, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , RECENT REPAIRS: check engine, P0579 speed control switch 1, P0456 Evap System small leak, P0591 speed control switch 2, PROBLEMS: exhaust manifold leaks, all 4 ball joints, left outer tie rod, alignment, hood chips, both bumpers dents/rusted, both front fenders rusted-holes, roof small rust spots, tailgates dents/chips/bezel broken, spare tire loose in box may not be compatible with unit, wheel wrench missing, jack & tools under driver seat, windshield chips, plate light, hole in driver seat, power invertor under right front seat, parking lots dent & scratches>, As is, Where is	302,683 Kms	3C6TD5CT8CG189315	CVA	438066 TOW	2001-989 ONLY 114-6



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
3,441.99 X-035	Truck 2006 FORD F150 4WD, super cab, has back seat, 6'6" box 5.4L V8 gas auto air, tilt, cruise, AM/FM radio front tow hooks, grille inserts, mud flaps, hitch, trailer wiring, metal plate protector on tailgate , Brown , Passed SGI Inspection., RECENT REPAIRS: pads & rotors, all 4 caliper pins , PROBLEMS: poor brakes- feels soft, hood dents/scratches, both bumpers rust/bent /scratches, all 4 fenders rust/scratches/paint peeling, all 4 doors chips/road rash, roof rust spots/1 hole sealed, tailgate paint peeling, 2 spare tires locked & chained to box- may not be compatible with vehicle, windshield chips, driver seat ripped, passenger seat stained, parking lot dents & scratches>, As is, Where is	273,161 Kms	1FTPX14526NB52024	CVA	438655 PASSED SGI , 114-2	2002-1172
4,077.12 X-067	Truck 2008 FORD F250 S/D 4WD, crew cab, has back seat, 6'7" box 5.4L V8 gas auto air, tilt, cruise, AM/FM/CD player, PL, PM, PW, power driver seat front tow hooks, grille inserts, side steps, mud flaps, hitch, trailer wiring, computer stand, Yukon side mounted tool box's latches not working/box's condition unknown , Blue , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front sway bar bushing, rear axle seal, brake shoes oil soaked, back park brakes seized, left front locking hub not unlocking, license plate light gone, hood chips/scratches/dents, rear bumper dents, all fender rust/chips/scratches, all doors chips/dents/road rash, roof scratches/rust spots, tailgate will not open, spare tire loose in box- may not be compatible with vehicle, cab corners road rash, parking lot dents & scratches>, As is, Where is	233,679 Kms	1FTSW21548EE38757	CVA	433067 TOW ONLY, 111-1	2002-1188

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,352.51 X-005	Truck 2010 FORD F250 SD RWD, super cab, has back seat, 8' box 6.4L V8 diesel auto air, cruise, tilt, AM/FM radio, PL, PM, power front windows, heated mirrors front tow hook, grille inserts, side steps, hitch, trailer wiring, Green , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Engine has issues, metal filing in the oil, will not start unless boosted, batteries will not charge/has connection problem, other problems may exist, exhaust manifold bolts broken, TPMS fault, driver seat cover torn, interior lights inoperative, both rear flaps missing, both bumpers damaged, tailgate will not open/badly dented/missing molding, minor cosmetic damages, hole from antenna, spare tire loose in box-may not be compatible with vehicle, cab corners rusted, holes in both box rails & bed of box, parking lots dents & scratches>, As is, Where is	231,703 Kms	1FTSX2AR9AEA01455	CVA	451252 TOW ONLY, 108-3	2001-1084
3,851.00 X-066	Truck 2006 GMC Sierra 2500HD 4WD, ext cab, has back seat, 8' box 6.0L V8 gas auto dual zone air, tilt, cruise, AM/FM/CD player, PL, vinyl back seat front tow hooks, side steps, wheel flares, mud flaps, hitch trailer wiring, electric trailer brake , White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear shocks, hood chips/dents/paint peeling, both bumpers dents/scratches/rust/holes, left rear fender chips, left rocker rusted, driver door rusted, roof rust spots/3 holes sealed, tailgate chips, wheel wrench & jack loose under back seat, box bed holes/cracked driver side/lower sides road rash, windshield cracked, parking lot dents & scratches>, As is, Where is	186,764 Kms	1GTHK29U46E274442	CVA	430249 TOW ONLY, 111-2	2002-1187

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
4,277.12 X-036	Truck 2008 GMC Sierra 3500 4WD, crew cab, has back seat, 8' box 6.0L V8 gas auto air, tilt, cruise, AM/FM radio, PL white Leer topper- condition unknown, side steps, mud flaps, grille inserts, trailer hitch, trailer wiring, electric trailer brake, cargo pull out - condition unknown, front seat covers, , Red , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: broken exhaust manifold bolts, all 4 rotors rusted & grooved, exhaust leak, steering box leaking, tire uneven wear, hood chips/dents/scratches, both bumpers dents/scratches, all 4 fenders chips/rust/road rash, all 4 doors chips/scratches/road rash, roof scratches/road rash, tailgate loose/chips/scratches, wheel wrench & jack loose under back seat, windshield chips, rear seat stained, license plate loose, tire balance brakes, wiper blades, parking lot dents & scratches>, As is, Where is	234,866 Kms	1GTHK33K98F218488	CVA	434180 TOW	2002-1173 ONLY, 114-1
4,279.79 X-026	Truck 2008 CHEVROLET Colorado 4WD, crew cab, has back seat, 5' box 3.7 L L5 gas auto air, tilt, cruise, AM/FM/CD/MP3 player, PL, PM, PW, keyless entry-2 fobs front tow hooks, sides steps, mud flaps, headache rack, beacon, hitch, trailer wiring, computer stand , Grey , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front sway bar links, park brake not holding, TPMS light on, rear tires poor, hood chips, both bumpers light scratches/dents, all fenders chips/scratches/dents/road rash/rust, left rocker scratches, driver door chips, right rear door rust, roof dents/1 hole sealed, tailgate dents/scratches/corner bent, windshield chips, right rear cab corner rusted, parking lot dents & scratches>, As is, Where is	230,881 Kms	1GCDT33E388222871	CVA	433984 TOW	2002-1163 ONLY, 115-4

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
3,627.12 X-020	Truck 2009 CHEVROLET Silverado 1500 LT 4WD, ext cab, has back seat, 6'7" box 5.3L V8 gas auto air, tilt, cruise, AM/FM/CD player grille inserts, hitch, trailer wiring, front tow hooks, Black , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both front lower ball joints loose, both rear brake drums rusted, right rear axle seal leaking on to brake shoes, left tail lamp cracked, both front door weather stripes torn, front left fender rusted out, wheel alignment, vibrations at highway speed, hood chips/scratches, both bumpers scratched/rear bent, all fenders chipped/rusted/not secured, both rockers rusted, both right doors all doors rusted/duraguard peeling, roof paint peeling/rusted spots, tailgate scratches/rust, rear seat cushion ripped, driver seat back torn/broken, holes in right front seat, both box rails scratched/dented/paint worn, parking lot dents & scratches>, As is, Where is	163,906 Kms	1GCEK19089Z240317	CVA	436664 TOW	2002-1157 ONLY, 117-2
3,727.12 X-077	Truck 2009 CHEVROLET Silverado 1500 4WD, ext cab, has back seat, 6'6" box 5.3L V8 gas auto air, tilt, cruise, AM/FM/CD player, PL, PW, PM front tow hooks, front & rear hitch receiver, trailer wiring, side steps, mud flaps, Duraguard on bottom sides, Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, left upper ball joint, left park brake cable, left exhaust manifold leaking, tire light on, drivers sun visor clip, hole in grille, hood chips/scratches, rear bumper pitted/rusted, all fenders scratches/dents/road rash, both rockers rusting, all doors rust/dents/scratches, roof scratches/2 holes sealed, tailgate chips/clear coat peeling/molding broken, driver's cushion worn, jack loose under back seat, holes in dash & headliner, missing jump seat, box rails dented/small holes, inside box scratched/holes drilled, parking lot dents & scratches>, As is, Where is	294,181 Kms	1GCEK19009Z240960	CVA	436326 TOW	2004-024 ONLY, 120-2

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>3,002.12 X-078</b>	Truck 2009 CHEVROLET Silverado 1500 RWD, ext cab, has back seat, 6'6" box 5.3L V8 gas auto air, tilt, cruise hitch, trailer wiring, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right front seat belt frayed, rotors rusted, drums worn/deep grooves, rear axle seals, transmission lines, bent rear bumper, driver seat cushion has been stitched to repair worn seat, hood chips/scratches, both bumpers pitted/scratched/dented, rear fenders bent at bumper, roof antenna/small rust spots, tailgate bent/scratched, windshield cracked, all seats stained, parking lot dents & scratches>, As is, Where is	205,573 Kms	1GCEC19059Z240269	CVA	451419 TOW	2004-037 ONLY, 123-2
<b>2,027.12 X-045</b>	Truck 2009 CHEVROLET Silverado 1500 RWD, ext cab, has back seat, 8' box 5.3L V8 gas auto air, tilt, cruise, AM/FM radio, PW, PL, PM grille inserts, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: large hole in front floor board, driver seat hole-metal frame visible, right front door binding with right front fender, window switch for right rear door loose, holes drilled in box bed, small crease in right side cab corner, hood chips/scratches, front bumper chips/rust spot, both right doors small crease, roof rust spots, windshield chips, right front back rest handle broken, parking lots dents & scratches> , As is, Where is	273,982 Kms	1GCEC19029E154022	CVA	451625 TOW	2002-1129 ONLY, 53-3

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5,727.12 X-082	Truck 2012 DODGE Ram 2500 4WD, crew cab, has back seat, 6'2" box with plywood liner 5.7L V8 gas auto air, tilt, cruise, AM/FM/CD player, PW, PL, PM, heated mirrors front tow hooks, side steps, mud flaps, grille inserts, hitch, trailer wiring, electric trailer brake, headache rack, beacon, Brown, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, drivers front axel seal leaking, rear rotors have high rust ridge, torque convertor leaking, transmission lines leaking, driver front mirror cracked, windshield cracked, all fenders rust/hails dents, grille paint peeling, hood hail dents, both bumpers rusted, roof hail dents, tailgate dents/rust/broken molding/won't open, spare tire missing, driver seat cushion worn to frame, parking lot dents & scratches> , As is, Where is	260,868 Kms	3C6TD5CT3CG195037	CVA	438140 TOW ONLY, 122-3	2004-030
2,877.12 X-011	Truck 2005 FORD F150 4WD, super cab, has back seat, 6'5" box 5.4L V8 has auto air, cruise, tilt, AM/FM radio front tow hooks, hitch, trailer wiring, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right inner tie rod, parking brake hardware not holding, brake shoes & drums worn out, brake cables seized, belt, left reverse light, hood dents, rear bumper dents, both left fenders chips/rusted, left doors chips/rusted, driver seat sagging/hole stitched, roof rusted/2 holes sealed, tailgate bent/scratched/chipped, wheel alignment, windshield cracked, parking lots dents & scratches> , As is, Where is	270,059 Kms	1FTPX14535NB71471	CVA	438010 TOW ONLY, 104-3	2001-1109

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,897.12 X-044	Truck 2006 FORD F150 RWD, super cab, has back seat, 6'6" box 4.6L V8 gas auto air, tilt, cruise, after market AM/FM/CD player box liner, grille inserts, tool box behind cab, side steps, mud flaps, hitch, trailer wiring, electric trailer brake, headache rack, beacon , Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: power steering pressure hose leaking, both battery connector wires corroded, rear differential pinion bearing loose, tires, transmission lines leak oil pan, hood scratches, both bumpers rusted, all fenders badly rusted, all door rusted, roof rust spots/1 hole sealed, tailgate dents/rusted/missing molding, spare tire loose in box- may not be compatible with vehicle, windshield cracked, hole in driver seat cushion showing frame, parking lots dents & scratches>, As is, Where is	285,843 Kms	1FTRX12W66NB52032	CVA	499558 TOW ONLY, 53-4	2002-1128
2,825.00 X-083	Truck 2006 FORD F150 RWD, supercab, has back seat, 6'6" box 4.6L V8 gas auto air, tilt, cruise, AM/FM radio partial phone cradle & speaker, hitch, trailer wiring, Romaflex rubber mat on box floor , White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: driver seat worn, both bumpers rust/scratches/plastic trim loose, all fenders rust/chips/road rash, front doors dents in trim/weather gasket loose, roof rust, tailgate dents, front of box dented/bent, windshield cracked, parking lot dents & scratches> , As is, Where is	196,207 Kms	1FTRX12W56FB08646	CVA	499400 TOW ONLY, 123-5	2004-034
2,702.12 X-084	Truck 2006 FORD F150 RWD, supercab, has back seat, 6'6" box 4.6L V8 gas auto air, tilt, cruise phone cradle & speaker, computer stand, mud flaps, hitch, trailer wiring , White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left outer tie rod, left plate light, front tires mismatched, windshield cracked, hood chips, both bumpers chips/scratches/rust spots, rear fenders rusting, roof rust spots, wires have been cut near hitch, parking lot dents & scratches> , As is, Where is	163,709 Kms	1FTRX12W76FB08647	CVA	499426 TOW ONLY, 123-3	2004-036

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,251.51 X-052	Truck 2009 FORD F150 RWD, supercab, has back seat, 6'6" box 4.6L V8 gas auto air, cruise, tilt, AM/FM radio, PL, PM, PW gull wing tool box mounted behind cab-condition unknown, Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, exhaust manifold bolts broken, battery cables corroded, all rotors rusted, PS pressure hose leaking, park break inoperative, engine ticking noise, brake noises, license plate lamps & front side markers inoperative, grille broken, hood chips, bumper chips/rust spots, all fenders rust/scratches, both rockers rusted, both left doors rust/dents, roof 1 hole sealed, tailgate rust/paint chips, cab corners rusted, windshield chips, left mirror housing/glass broken, driver seat cushion worn, front valance broken, wiper blades, parking lots dents & scratches>, As is, Where is	262,211 Kms	1FTRX12829FB44526	CVA	451138 TOW	2002-1136 ONLY, 52-3
4,302.12 X-086	Truck 2010 FORD F250 4WD, super cab, has vinyl back seat, 6'6" box 5.4L V8 gas auto air, tilt, cruise, AM/FM/CD player, PM, PL, power front windows grille inserts, mud flaps, side steps, front tow hooks, hitch, trailer wiring, Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right inner & upper tie rods, front pads & rotors, manifold leaks, rear pinion seal leaking, driver's tail light, both plate lights, right side marker, front links, TPMS light on, front differential, hood chips/scratches, both bumpers rust/dents/tied down, all fenders road rash/dents/rust, all doors chips/road rash, 2 holes sealed in roof, tailgate dent/chips/missing molding, wheel wrench & jack missing, windshield cracked/chipped, missing jump seat, holes in dash & headliner, driver seat worn & missing trim, cab corners rusted, parking lot dents & scratches>, As is, Where is	239,614 Kms	1FTSX2B5XAEA01427	CVA	435872 TOW	2004-018 ONLY, 118-2



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
4,377.12 X-043	Truck 2009 FORD F250 SD 4WD, crew cab, has back seat, 6'7" box 5.4L V8 gas auto air, tilt, cruise, AM/FM radio, PW, PL, PM front tow hooks, front hitch receiver, grille inserts, mud flaps, side steps, rear hitch, trailer wiring, trailer tow mirrors, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: exhaust leak at engine, wheel alignment, high mount stop lamp inoperative, both license plate lights outs, alignment out of spec, windshield cracked, grille cracked, hood chips/scratches, both bumpers dents/scratches/rusted, rear bumper pad loose & cracked, all fenders dents/chips/rusted, doors 4 holes drilled/chips/road rash, roof 13 holes sealed, tailgate difficult to open/scratches/chips, missing jump seat, windshield cracked, parking lots dents & scratches>, As is, Where is	269,538	1FTSW21599EB16438	CVA	435336 TOW	2002-1127 ONLY, 53-5
4,127.12 X-053	Truck 2006 FORD F350 SD 4WD, crew cab, has back seat, 8' box 6.8L V10 gas auto air, tilt, cruise, AM/FM/CD player, PL, PM, PW grille inserts, front tow hooks, hitch, trailer wiring, trailer brake, wheel flares, Red , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: front steering stabilizer shock, transmission cooler leaking, left rear window inoperative, spare tire not mounted, tailgate tied shut, left rear leaf spring out of alignment, license plate lamp missing, driver door weather stripped, wheel alignment out of spec, left windshield washer nozzle, hood chips/scratches, both bumpers chips/bent/scratches, rear bumper pad broken, Duraguard on lower area of both sides of unit, right rear door missing inside trim, rear seat stained, spray in box liner, parking lots dents & scratches>, As is, Where is	177,999	1FTWW31Y36ED9036	CVA	438960 TOW	2002-1138 ONLY, 52-1

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
4,195.00 X-087	Truck 2002 FORD F550 RWD, regular cab, utility body with max lift crane, dual rear wheels 6.8L V10 gas auto air, tilt, cruise, after market AM/FM radio front tow hooks, side steps, hitch, grille inserts, trailer tow mirrors, max lift crane Cobra 3304W condition unknown, HD rear bumper, 2 beacons , White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right E brake cable out, power steering leaking, steer box leaking, steering slab, left rear shock, right front sway bar, left exhaust manifold bolt broken, left front tire RRI-LRO-2/32, tool box rusted through, reflectors, general utility body badly rusted/condition of components unknown, grille cracked, hood chips/dents, front bumper rusted through, all fenders rusted/missing badge, both front doors rusted through, 1 hole in roof sealed, moisture in right front signal , first aid kit & fire extinguisher, windshield cracked driver side mirror housing cracked, parking lot dents & scratches> , As is, Where is	286,353 Kms	1FDAF56S62EC77004	CVA	515650 TOW	2004-015 ONLY, 118-5
3,802.12 X-009	Truck 2009 GMC Sierra 1500 4WD, ext cab, has back seat, 6'6" box 5.3L V8 gas auto air, cruise, tilt, AM/FM/CD player, PL, PM, PW front tow hooks, hitch, trailer wiring, Grey, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: all 4 ball joints, 3rd brake light, plate light, missing jump seat, grille cracked, hood chips/missing deflector/large dent & out of alignment, front bumper dents, rear bumper dents/pad loose, both rear fenders road rash/ bent, all 4 doors rusted/dents/road rash, roof rusted/ 2 holes sealed, tailgate both corner bent, holes in box rail behind cab, windshield chips, parking lots dents & scratches>, As is, Where is	249,206 Kms	1GTEK19019Z263244	CVA	436516 TOW	2001-1107 ONLY, 104-5

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
3,827.12 X-010	Truck 2009 GMC Sierra 1500 4WD, ext cab, has back seat, 8' box 5.3L V8 gas auto air, cruise, tilt, AM/FM radio front tow hooks, hitch, trailer wiring, Linex spray box liner , Blue , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left lower ball joint out of spec, rear shock leaking, RR & LF axle seals leaking, brake pulsation, tailgate not secure/will not close, spare tire hoist broken, right front side marker, plate light, rear mud flaps torn off, rear differential, transfer case low, tire balance, hood chips/scratches/ missing deflector, both bumpers dents/pads loose/rear bumper bent, all 4 fenders dents/scratches/rusted, RF fender rusted through, right 1/4 bent behind wheel, driver door opening weather stripping, all 4 doors rusted/scratches/road rash, roof rusted/scratches, tailgate dents/scratches/cap broken, spare tire loose in box-may not be compatible with vehicle, windshield chips, parking lots dents & scratches> , As is, Where is	276,358 Kms	1GTEK19019E149333	CVA	435203 TOW	2001-1108 ONLY, 104-4
2,927.12 X-012	Truck 2005 GMC Sierra 2500HD 4WD, ext cab, has back seat, 6'7" box 6.0L V8 gas auto dual zone air, cruise, tilt, AM/FM/CD player, PL, PM, power front windows front tow hooks, hitch, trailer wiring, mud flaps , Brown , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: headlights align, slight play in front door pins, battery marginal, tire cupped, spare tire hoist broken, cab corners rusted, hood chips/dents, both bumpers dents/rusted, all 4 fenders paint chips/dents/rusted, both rockers rusted, all 4 doors road rash/rusted, roof 4 holes sealed, tailgate rusted/missing bezel around handle, spare tire mounted in box, wheel wrench & jack loose under back seat, windshield chips, parking lots dents & scratches>, As is, Where is	220,183 Kms	1GTHK29U35E313293	CVA	437855 TOW	2001-1110 ONLY, 104-2

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
2,577.12 X-074	Truck 2006 GMC Sierra 2500HD 4WD, ext cab, has back seat, 8' box 6.0L V8 gas auto dual zone air, cruise, tilt, AM/FM/CD player, PL mud flaps, side steps, hitch, trailer wiring, trailer brake, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: exhaust leak at connectors, right rear door outside handle broken, difference of tread between front & rear tires, rockers rusted out, hood chips/dents/paint poor, front bumper rusted/ hole, both rear fenders scratches/road rash, all 4 doors chips/road rash/rusted, roof rust spots/dents/2 holes sealed, tailgate paint chips, wheel wrench under backseat, hole in housing of drivers mirror, rip in driver seat, holes in bed of box, head liner loose, parking lots dents & scratches> , As is, Where is	236,101 Kms	1GTHK29U46E274019	CVA	439877 TOW	2001-1118 ONLY, 103-1
WD 4,027.12 X-013	Truck 2006 GMC Sierra 2500HD 4WD, ext cab, has back seat, 8' box 6.0L V8 gas auto dual zone air, cruise, tilt, AM/FM radio side steps, mud flaps, headache rack, beacon, hitch, trailer wiring, electric trailer brake, hazard lights mounted in grille & headache rack, Blue , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: left lower ball joint, battery weak, front pads & rotors abnormal wearing/rusted, no interior light, front parking lamp, right front seat holes, wiper chatter, hood chips/scratches/dents, both bumpers dents/lower valance on front cracked, all 4 fenders chips/dents/scratches/road rash, all 4 doors dents/scrapes/scratches/road rash, roof scratches/antenna/rusted, tailgate dents/scratches/ missing bezel around handle, wheel wrench missing, both LF & RF seat cushion holes, windshield cracked, both box rails dents, driver side headliner loose, cab behind right rear door scratched, parking lots dents & scratches> , As is, Where is	274,673 Kms	1GTHC29UX6E261224	CVA	499756 TOW	2001-1111 ONLY, 104-1

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>4,427.12 X-088</b>	Truck 2009 GMC Sierra 2500HD 4WD, crew cab, has back seat, 6'6" box 6.0L V8 gas auto air, tilt, cruise, AM/FM/CD player, PW, PL, PM, power front seats grille inserts, front tow hooks, side steps, front receiver, rear hitch, trailer wiring, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , RECENT REPAIRS: SES light on corrected, PROBLEMS: both front axles, exhaust manifold, tires, left rear window, driver seat ripped, wheel alignment, windshield cracked, grille chrome peeling, hood stone chips, front bumper rusted, rear bumper pad loose/bent, all fenders rust/dents, all doors dents/rust, roof scratches/rust/1 hole sealed, tailgate paint poor/loose/dents, spare tire loose in box may not be compatible with vehicle, wheel wrench missing, front lower variance cracked & loose, both box rails - paint poor & rusted, holes & cracks front of box, missing jump seat, holes in headliner, missing headliner consul, parking lot dents & scratches >, As is, Where is	253,875 Kms	1GTHK43K89F161241	CVA	435674 TOW	2004-035 ONLY, 123-4
<b>5,077.12 X-041</b>	Truck 2009 GMC Sierra 3500 4WD, crew cab, has back seat, 8' box 6.0L V8 gas auto air, tilt, cruise, AM/FM radio, PL, PM, PW front tow hooks, side steps, front mud flaps, grille inserts, hitch, trailer wiring, trailer brake, headache rack, high receiver on front, Black , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rear shocks, park brake, park brake cables, rotors, rear drums, high mount outlet reverse light, TPMS light on, front mud flaps worn, rear mud flaps missing, hood chips/scratches, holes in rear bumper pad, all 4 fenders chips/scratches/dents, all 4 doors chips/scratches/road rash, roof scratches/dents/rust spots, tailgate loose/rattling/dented/scratched, spare tire loose in box-may not be compatible with vehicle, wheel wrench & jack loose under back seat, windshield cracked, both front seats ripped/worn, seat belt frayed, inside box scratched, wheel well dented, driver seat cushion trim missing, parking lots dents & scratches>, As is, Where is	260,447 Kms	1GTHK73K69F167511	CVA	436193 TOW	2002-1124 ONLY, 54-2

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
4,100.00 X-089	Van 2003 CHEVROLET Express 3500 RWD, cargo, 135" wheel base 6.0L V8 gas auto air, tilt, cruise, AM/FM radio partial cargo barrier, metal shelving with drawers, bars on rear windows, hitch, trailer wiring, electric trailer brake , White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: large hole in left rear cargo area, left front wheel bearing, slight play in right lower ball joint, missing rear heater motor, wiper blades, hood chips/scratches, front bumper rusted, rear fenders paint peeling/road rash/rust, right rocker road rash, right rear door paint peeling, roof scratches/rust spots/paint peeling, tailgate paint peeling, no first aid kit or fire extinguisher, windshield chips, parking lot dents & scratches>, As is, Where is	153,305 Kms	1GCHG35U831172982	CVA	416032 TOW ONLY, 122-6	2004-027
5,027.00 X-090	Van 2003 CHEVROLET Express 3500 Cub Van RWD, dual rear wheels, 155" wheel base 6.0L V8 gas auto air, tilt, cruise, unicell van body-with access to cab 14'L x 7'6"w x 7'h, electric lift has 1600 lbs max capacity fiberglass interior, plywood floors, roll up cargo door, rubber mat on floor, Ultron electric lift will move up & down/fold out ramp appears seized-condition unknown, White , Passed SGI Inspection., RECENT REPAIRS: hyd brake system, tires, & suspension fixed, fire extinguisher/hazard kit, PROBLEMS: right front door trim panel broken, hood chips/dents, front bumper rust/pad cracked & loose, front fenders paint chips, left rocker rusted, front doors rust, roof rust spots, spare tire missing, wheel wrench & jack missing, first aid kit & fire extinguisher missing, plywood cab floor worn, parking lot dents & scratches>, As is, Where is	50,277 Kms	1GBJG31UX31114139	CVA	515916 PASSED SGI,123-6	2004-033

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5,302.12 X-091	Van 2009 CHEVROLET Express 3500 Cub Van RWD, dual rear wheels 6.0L V8 gas auto air, tilt, cruise, AM/FM radio, backup assist, PL, PM, PW, unicell van body-12'L x 7'6" w x 6'6" h, liftgate has 3000 lbs max capacity roll up cargo door, right side door with steps, rear heater, plywood walls, fiberglass interior, Waltco lift gate-works but platform will not open , White , Passed SGI Inspection., , PROBLEMS: differential noise fluid/discolored, hood chips/dents, front bumper pitted/chipped, roof top right scraped, wheel wrench & jack missing, first aid kit & fire extinguisher missing, windshield chips parking lot dents & scratches>, As is, Where is	119,444 Kms	1GBHG31K191176146	CVA	518274	2004-032 PASSED SGI, 122-1
527.12 * 12-023	Van 2006 DODGE Caravan 2WD, 7 passenger 3.3L V6 gas auto air, cruise, tilt, AM/FM/CD player, PL, power front windows roof rack, Silver , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: rockers rusted, front struts leaking, oil pan gasket sweating, right front window won't roll down, hood chips/scratches, both bumpers chips/scratches, all fenders dents/rusted/holes, all doors rusted/creased, tailgate scratches/rusted through, windshield chips, driver side windshield molding loose, parking lots dents & scratches>, As is, Where is	283,761 Kms	1D4GP25R76B680900	CVA	192294	TOW 2001-1071 ONLY, 120-2
552.51 * 11-063	Van 2007 DODGE Caravan 7 passenger 3.3L V6 gas auto air, cruise, tilt, AM/FM/CD player, PM, PL, power front windows/rear vent windows , Gold, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both lower ball joints, right outer tie rod, wheel alignment, grille chips, hood chips/scratches/dents/rusted, both bumpers chips/dents, all 4 fenders rusted, both rocker panels rusted, all 4 doors dents/rusted, tailgate rusted, windshield cracked, wiper blades, right front seat ink spots, parking lots dents & scratches>, As is, Where is	272,150 Kms	1D4GP25E97B206929	CVA	192906	TOW 2001-1026 ONLY, 123-8

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
2,127.12 X-061	Van 2007 DODGE Caravan 7 passenger 3.3L V6 gas auto air, tilt, cruise, AM/FM/CD player, power window vents, PM, PL, Red, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both inner tie rods, PS return line leaking, wheel alignment, both sliding door locks broken, passenger sliding door doesn't opening, hood chips/scratches/paint bubbling, both bumpers chips/scratches/rear bumper cracked with holes, all 4 fenders scratches/scrapes/road rash, both rocker rusted, all doors chips/scratches/rust, tailgate rust/dents/scratches, windshield chips, right front storage compartment broken, 2nd row back rest ripped torn/head rest torn, left rear inside door panel broken, inside trim on both B pillars broken, interior very dirty, rear door lock buttons missing, parking lot dents & scratches>, As is, Where is	235,606	1D4GP25E17B206942	CVA	192781 TOW ONLY, 111-7	2002-1182
2,027.12 X-016	Van 2009 DODGE Grand Caravan 2WD, 7 passenger 3.3L V6 gas auto air, tilt, cruise, AM/FM/CD player, PM, PL, power front window rear HVAC, 2nd & 3rd row stow & go, Beige, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES light on, P0305 cylinder 5, P0300 random misfire, front pads worn at angle, front rotors rusted & grooved, missing wires/plugs new, hood chips/dents/scratches, both bumpers chips/scratches/rear cracked, all fenders rusted/missing molding, both left doors rust/road rash, left rear door molding loose, left rear tail light lense broken, windshield chips, parking lot dents & scratches>, As is, Where is	251,456	2D8HN44EX9R681760	CVA	171462 TOW ONLY, 117-6	2002-1153



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>4,052.12 * 10-021</b>	Van 2009 DODGE Grand Caravan Cargo FWD 3.3L V6 Gas auto air, cruise, tilt, AM/FM/CD player, power front windows, PL, PM cargo barrier, metal shelving, steel floor, roof ladder rack with amber beacon, map box, computer stand, White, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: Battery weak (PF 78 DT), inner tie rod, front motor mount support damage, front bumper damage, right side sliding door and C pillar dented, drivers seat ripped/worn, hood paint bubbling, both bumpers cracks/scratches/dents, RR fender dented, RR door dented, roof 3 holes sealed, parking lot dents & scratches>, As is, Where is	81,304	2D4HN11E79R617633	CVA STEL	171512	1910-699 297211 TOW 1909-626 ONLY, 104.2
<b>2,477.12 X-062</b>	Van 2009 DODGE Grand Caravan SE FWD, 7 passenger 3.3L V6 gas auto air, tilt, cruise, AM/FM/CD player, PM, PL, power front windows rear HVAC, 2nd & 3rd row stow & go , Beige, TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: right sun visor clip, hood dents/paint bubbling, both bumpers chips/scratches, both left fenders scratched, both left doors rust at bottom, roof dents, tailgate glass scratched, windshield chips, parking lot dents & scratches>, As is, Where is	290,877	2D8HN44E19R681761	CVA	173237	TOW 2002-1183 ONLY, 111-6

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
2,727.12 X-046	Van 2007 FORD Econoline E350 SD EXT RWD, Wagon, 11 passenger 5.4L V8 gas auto air, tilt, cruise, AM/FM radio, power front windows & locks rear HVAC, cargo barrier behind last bench seat, beacon on roof, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: sway bar bushing, rotors & pads, RR door will not open from the outside, missing rear bench seat, right rear tail light broken, rear view mirror, 1st bench seat ripped/worn, arm rest on right front seat broken, 3 rips in head liner, hood chips/dents/scratches, both bumpers chips/rusted/bent, all 4 fenders chips/dents/loose/rusted, both rockers rusted/chipped, all doors chipped/rusted, roof dents/scratches/2 holes sealed , tailgate chipped/rusted, first aid kit & fire extinguisher missing, windshield cracked, right front mirror cracked, both front seats ripped, hazard switch, missing mud flaps, 2 dash vents missing, wiper blades, parking lots dents & scratches>, As is, Where is	239,476	1FBSS31L77DB24996	CVA	423889 TOW	2002-1130 ONLY, 53-2
3,502.12 X-042	Van 2007 FORD Econoline E350 SD EXT RWD, Wagon, 15 passenger 5.4L V8 gas auto front air, rear HVAC, tilt, cruise, AM/FM radio, PL, PW hitch, trailer wiring, mud flaps, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: both upper ball joints, sway bar bushing, front twin I suspension beam, front brake pads, rotors, rear park shoes, drive belts, last bench seat doesn't anchor properly, hood chips, both bumpers rusted/cracked/bent, air dam under front bumper cracked, both rear fenders road rash, roof hail dents, tailgate rusted/small dents, first aid kit & fire extinguisher removed, windshield cracked/chipped, parking lots dents & scratches>, As is, Where is	174,343	1FBSS31L77DB24979	CVA	423046 TOW	2002-1125 ONLY, 54-1

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1,002.12 X-047	Van 2008 FORD Econoline E350 SD EXT RWD, Wagon, 11 passenger 5.4L V8 gas auto air, tilt, cruise, AM/FM/CD player, power front windows, PL, PM rear HVAC, grille inserts, beacon on roof, hitch, trailer wiring, White , TOW ONLY, Failed SGI Inspection. Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs. , , PROBLEMS: SES & TPMS light on, P0446 evap system malfunction, P1000 OBDII test incomplete, P0446:EF, right lower ball joint, right outer tie rod, rear leaf spring, front rotors, missing last bench seat, parking brake not holding, right rear cargo door handle broken, grille chrome peeling, hood paint chips & scratches, both bumpers rusted/bent/ front trim missing, all fenders paint peeled/rusted, left rear fender dented & bent, both rockers rusted, all 4 doors paint poor/dents/rusted, roof 2 holes sealed/rusted at front, tailgate paint poor/bent/rusted, fire extinguisher & first aid kit missing, windshield cracked/chips, left mirror housing cracked, driver seat worn/has hole/missing arm rest, headliner roof vent missing, wiper blades, parking lots dents & scratches>, As is, Where is	302,359	1FBSS31L58DB48733	CVA	424390 TOW	2002-1131 ONLY, 53-1

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>REGINA, Central Services, SaskSurplus Sales Lot, 500 McLeod Street - Miscellaneous Items and Equipment.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact SaskSurplus (306) 787-2062 or (306) 798-3306.</b>						
32.75	X-101	Arrow Traffic Warning Light Model 58019 SWS Condition Unknown, colour Amber Lights , , , , , Poor		CVA	SS2359	2003-1215
No Bid	X-392	Book Intermediate Accounting older book , , , , , fair		CS SaskSurplus	ss3407	2004-093
No Bid	X-393	Book Road Kill , , , , , fair		CS SaskSurplus	ss3406	2004-093
1.25	X-394	Brief Case black 18x12.5x4" , , , , , fair		CS SaskSurplus	ss3405	2004-093
1.25	X-395	Brief Case black 18x12.5x5" , , , , , fair		CS SaskSurplus	ss3404	2004-093
1.25	X-396	Brief Case brown 18x13x3.75" , , , , , fair		CS SaskSurplus	ss3403	2004-093
56.00	X-240	Cart Model: 526 Lakeside, stainless steel 30.5"w x 17.75"d x 34"h, 3 shelves guarded, 4 casters , , , , , Fair		SS VVC	ss3256	2003-1218
40.00	X-241	Cart Rubbermaid 33.5"w x 18.75"d x 35.75"h, 4 casters, 3 shelves, open sided , , , , , Fair		SS VVC	ss3251	2003-1218
28.40	X-242	Cart Rubbermaid 40.25"w x 20"d x 33.75"h, 4 casters, 3 shelves, open sided , , , , , Fair		SS VVC	ss3250	2003-1218
40.00	X-243	Cart Rubbermaid 40.5"w x 20"d x 33.75"h, 4 casters, 3 shelves, open sided , , , , , Fair		SS VVC	ss3252	2003-1218
40.00	X-244	Cart Rubbermaid 40.5"w x 20"d x 33.75"h, 4 casters, 3 shelves, open sided , , , , , Fair		SS VVC	ss3253	2003-1218
21.00	X-245	Cash Box black metal, removable tray, lock & key , , , , , Good		SS VVC	ss3359	2003-1218
7.50	X-247	Cash Boxes Lot of 3 black metal, 2/3 boxes have removable trays, lock, no key , , , , , Good		SS VVC	ss3362	2003-1218

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5.00 X-248	Cash Boxes Lot of 2 black metal, removable tray, lock, no key , , , , , Good			SS VVC	ss3360	2003-1218
5.00 X-249	Cash Boxes Lot of 2 black metal, removable tray, lock, no key , , , , , Good			SS VVC	ss3361	2003-1218
4.00 X-250	CD Storage Box Plastic, with various CDs included (mainly country) 3 drawers, black , , , , , Fair			SS VVC	ss3238	2003-1218
21.51 X-254	Lawn Chair metal grey , , , , , Fair			SS VVC	ss3217	2003-1218
6.00 X-255	Lawn Chair plastic red , , , , , Fair			SS VVC	ss3218	2003-1218
No Bid X-256	Chair recliner/rocker, fabric purple, worn a bit on the upper back, dirty , , , , , Fair			SS VVC	ss3222	2003-1218
No Bid X-257	Chair recliner/rocker, leather purple, leather scraped & worn , , , , , Poor			SS VVC	ss3219	2003-1218
No Bid X-417	Chairs Lot of 4 Wood Frame, fabric covered armrests, non-adjustable, 4 casters, blue , , , , , Poor			SaskSurp lus	7-142	2005-105
11.63 X-270	Coat Rack metal 6 feet high , , , , , Fair			SS VVC	ss3317	2003-1218
15.75 X-271	Coffee Table wood 44.5"w x 24.5"d x 16"h , , , , , Poor			SS VVC	ss3296	2003-1218
No Bid X-397	Computer Arm Monitor mounting , , , , ,			CS SaskSurp	ss3370	2004-093
1.00 X-272	Decoration little Christmas wreath 16" diameter , , , , , Fair			SS VVC	ss3274	2003-1218
7.82 X-425	Dolly round, wood 23.5" diameter, 4 casters , , , , , Fair			SS VVC	SS3448	2006-112
No Bid X-275	Emergency Evacuation Bag green fabric, draw string closure, black fabric interior , , , , , Fair			SS VVC	ss3248	2003-1218
95.00 X-276	Exam Table Midmark 405 powered 4 drawers, patient weight max 300 lbs, table top height adjustment: 25" to 37", stirrups 4 lateral positions, dimensions: 27"w x 55"l, power requirements: 115 VAC, 50/60 HZ, 12.0 amps, in working condition , , , , , Good			SS VVC	ss3295	2003-1218
5.25 X-277	Fan Royal Sovereign, model: PFN-40B oscillating pedestal 16", 3 speed settings, adjustable head & height, unknown if working , , , , , Good			SS VVC	ss3318	2003-1218

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5.25 X-278	Fan Royal Sovereign, model: PFN-40B oscillating pedestal 16", 3 speed settings, adjustable head & height, unknown if working , , , , , Good			SS VVC	ss3390	2003-1218
24.40 X-426	Fan Torcan, model 1145 3 speeds, 1.5 amps, 120 volts 60 hz, brown & white, unknown is operational , , , , , Fair			SS VVC	SS3446	2006-112
11.00 X-279	Fan Westward, model: FA18P Westward oscillating pedestal 3 speed settings, adjustable head, unknown if works , , , , , Good			SS VVC	ss3391	2003-1218
No Bid X-295	Flashlight Eveready in working condition , , , , , Fair			SS VVC	ss3316	2003-1218
8.50 X-296	Fridge Danby, model: DCR34W compact 17.5"w x 18"d x 33.25"h, 3 shelves, white, unknown if operational , , , , , Fair		0103010100467	SS VVC	ss3228	2003-1218
8.50 X-297	Fridge General Electric, model: TACHSNYBW compact 18.5"w x 17.75"d x 33.5"h, 3 shelves , , , , , Fair		VV086422	SS VVC	ss3236	2003-1218
1.25 X-298	Garbage Cans Lot of 2 metal rusted at bottom, black , , , , , Fair			SS VVC	ss3242	2003-1218
1.25 X-299	Garbage Cans Lot of 2 plastic black, dirty , , , , , Fair			SS VVC	ss3241	2003-1218
No Bid X-203	Filter Honeywell, Model HRF-14 HEPA Universal Replacement and gasket, see photo for Models this will fit. , , , , , New - Unused			AG	CDP29189 SS3312	2002-1139
No Bid X-204	Filter Honeywell #38002 Pre-filter Universal Replacement, fits all round Honeywell HEPA Air Cleaner Models, and others , , , , , New - Unused			AG	CDP29190 SS3311	2002-1139
22.00 X-300	Bed Stryker hospital style 39"w x 84.25"l, 4 casters, head & foot board in poor condition, bed in fair condition, guards on bed sides, unknown if lift is working , , , , , Poor			SS VVC	ss3254	2003-1218
2.25 X-418	Lamps Lot of 2 brass, for end tables 25.5" tall, no shades, 23 watt florescent bulbs , , , , , Fair			SaskSurp lus	7-225	2005-105
No Bid X-432	Laptop Mount Ram brand approx. 10 x 10" to be mounted in a vehicle. Approx. 24 inches tall. , , , , , Poor			CVA	SS3340	2006-121
4.50 X-197	Cabinet for maps, metal, grey 16w x 39d x 52h, no key , , , , , Good			AG	CDP28718 ss3312	2004-039
22.22 X-128	Maps Lot of 426 Area (RM) Various locations. Usable and functional , , , , , Good			ENV	1	2003-1224
22.22 X-129	Maps Lot of 240 Forestry Various locations. Usable and functional , , , , , Good		Various Serial numbers (attached)	ENV	2	2003-1224

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>*MT</b>	<b>X-305</b>	Microwave Beaumark, model:EM0314B2-P 20.5"w x 14.75"d x 13"h, unknown if operational , , , , Fair		01912138000267	SS VVC	ss3234	2003-1218
	<b>1.65 X-306</b>	Microwave Oven Sanyo, model: EM-2520KA unknown if operational , , , , Fair		LR61682	SS VVC	ss3260	2003-1218
	<b>1.65 X-307</b>	Microwave Sunbeam, model: SMW769 18"w x 12"d x 11"h, scuffed on top, unknown if operational , , , , Fair		SBM307693766	SS VVC	ss3230	2003-1218
	<b>6.30 X-308</b>	Mirror black wood frame 14"w x 19"l , , , , Fair			SS VVC	ss3284	2003-1218
	<b>1.25 X-309</b>	Mirrors Lot of 2 pictures of a flower and a sailboat 18.25"w x 42.25"l , , , , fair			SS VVC	ss3363	2003-1218
	<b>31.00 X-310</b>	Music Instrument wooden temple blocks, percussion no brand, 4 blocks vary in size, 4 wooden mallets, cow bell, with stand , , , , Good			SS VVC	ss3358	2003-1218
	<b>No Bid X-312</b>	Oxygen Tank Cart metal mint green, rusted , , , , Poor			SS VVC	ss3392	2003-1218
	<b>No Bid X-313</b>	Piano wood, with stool 63"w x 29"d x 53"h, operational, extremely worn, out of tune , , , , Poor			SS VVC	X-V209	2003-1218
	<b>1.25 X-314</b>	Picture featuring a bar counter top 33.5"l x 17.25"w , , , , Good			SS VVC	ss3304	2003-1218
	<b>1.25 X-315</b>	Picture with Frame featuring flowers in a vase 19.5w x 23.5l , , , , fair			SS VVC	ss3366	2003-1218
	<b>1.25 X-316</b>	Picture with Frame featuring apples and grapes in a bowl 33.5"w x 25.5"l, red detailed frame, green mat , , , , Fair			SS VVC	ss3264	2003-1218
	<b>27.53 X-317</b>	Picture with Frame featuring 2 girls on a couch with presents gold frame, 31.5l x35.25w Certificate of Authenticity 30 of 250 , , , , fair			SS VVC	ss3364	2003-1218
	<b>1.25 X-318</b>	Picture with Frame featuring a field 39w x 39l, wooden frame , , , , fair			SS VVC	ss3365	2003-1218
	<b>1.25 X-398</b>	Picture with Frame featuring a waterfall 21.75"w x 36.5"l, metal frame , , , , fair			CS SaskSurplus	ss3368	2004-093
	<b>1.25 X-399</b>	Picture with Frame featuring a lake dock with boats 24.5"w x 20.5"l, metal frame , , , , fair			CS SaskSurplus	ss3367	2004-093

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5.30 X-400	Picture with Frame featuring Wascana park 20.75"w x 24.5"l, metal frame , , , , , fair			CS SaskSurplus	ss3369	2004-093
1.25 X-319	Picture with Frame featuring 3 children playing jacks, green wood frame with glass 15"x18" frame, 2" mat , , , , , Fair			SS VVC	ss3291	2003-1218
1.25 X-320	Picture with Frame featuring trees & flowers, black wood frame with glass 11"w x 23"l , , , , , Fair			SS VVC	ss3289	2003-1218
1.25 X-321	Picture with Frame featuring vases on table with flowers, wood & gold accent frame with glass 19.75"w x 19.75"l, 3" mat , , , , , Fair			SS VVC	ss3287	2003-1218
2.00 X-322	Pictures with Frames Lot of 2 featuring a balcony, wood & gold frames 11.8"w x 23.5"l , , , , , Fair			SS VVC	ss3286	2003-1218
2.00 X-323	Pictures with Frames Lot of 2 featuring fruit in cups, wood frames (worn in corners) with glass 19.75"w x 19.75"l, 3" mat , , , , , Fair			SS VVC	ss3285	2003-1218
2.00 X-324	Pictures with Frames Lot of 2 featuring a street scene, gold accented wood frame 16.5"w x 16.5"l , , , , , Fair			SS VVC	ss3292	2003-1218
2.00 X-325	Pictures with Frames Lot of 2 featuring park paths & trees, black wood frames with glass 11"w x 23"l , , , , , Fair			SS VVC	ss3288	2003-1218
2.25 X-419	Plants in Pots Lot of 2 artificial approx. 5 feet tall, in wicker basket , , , , , Fair			SaskSurplus	7-228	2005-105
No Bid * 11-135	Roof Rack Metal, with amber beacon Removed from 2008 Dodge Grand Caravan , , , , , Good			STEL	ss2786	2001-1102
6.00 X-327	Shoe Rack small, wood 27"w x 12"d x 26.75"h, chipped, scratched, 2 shelves , , , , , Fair			SS VVC	ss3221	2003-1218
78.88 X-433	Side Steps set of 2 Ford Factory removed from a 2019 Ford F150 XLT crew cab , , , , , Excellent		801,182	CVA	SS2781	2006-121
78.88 X-434	Side Steps set of 2 Ford Factory removed from a 2019 Ford F150 XLT crew cab , , , , , Excellent		801,192	CVA	SS2783	2006-121
98.89 X-435	Side Steps set of 2 Ford Factory removed from a 2019 Ford F250 crew cab , , , , , Excellent		801,157	CVA	SS2784	2006-121
98.89 X-410	Side Steps Set of 2 Ford Factory Removed from a 2019 Ford F250 crew cab , , , , , Excellent		801,319	CVA	ss3329	2004-088



	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
	98.89 X-411	Side Steps Set of 2 Ford Factory Removed from a 2019 Ford F250 crew cab , , , , , Excellent		801,313	CVA	ss3331	2004-088
	78.88 X-436	Side Steps set of 2 Ford Factory removed from a 2019 Ford Fi50 crew cab , , , , , Excellent		801,204	CVA	SS2785	2006-121
	78.88 X-412	Side Steps Set of 2 Ford Factory Removed from a 2020 Ford F150 XLT crew cab , , , , , Excellent		801,490	CVA	ss3330	2004-088
WD	81.00 X-102	Side Steps Set of 2 Removed from 2019 Chevy Silverado , , , , , New - Unused			CVA	SS1798	2003-1215
	1.25 X-328	Small Container wood 9.25"w x 9"d x 3.25"h , 2 removable shelves , , , , , Fair			SS VVC	ss3257	2003-1218
	No Bid X-420	Sofa 3/3 cushion, wood trim 83.5" x 31.5" x 25", green , , , , , Fair			SaskSurplus	7-241	2005-105
	125.50 X-329	Sofa Lot of 5 sections for a reception area approx. 12ft long, dark pattern , , , , , Fair			SS VVC	ss3350	2003-1218
	35.47 X-330	Stool medical swivel stool, vinyl adjustable, 5 casters, black , , , , , Good			SS VVC	ss3243	2003-1218
	16.00 X-331	Stool step stool, plastic black, dirty , , , , , Fair			SS VVC	ss3235	2003-1218
	7.25 X-427	Table metal 48"w x 24"d x 28.75"h, green & pink , , , , , Fair			SS VVC	SS3450	2006-112
	45.50 X-335	Table used for baking 21.25"d x 44.5"w x 33"h, 4 casters , , , , , Poor			SS VVC	ss3300	2003-1218
	10.25 X-421	Coffee Table wood brown, 42" x 26' x 17", bottom shelf , , , , , Fair			SaskSurplus	7-244	2005-105
	12.50 X-336	Coffee Table wood 35.5"w x 15"d x 22h, black, 2 shelves, not very sturdy , , , , , Fair			SS VVC	ss3302	2003-1218
	10.25 X-337	Coffee Table wood 45"w x 16"d x 17.5"h, scuffed on legs , , , , , Fair			SS VVC	ss3343	2003-1218
	6.25 X-338	Medical Side Table metal & laminate 32"w x 14.5"d x 32.5"h, 4 casters, paint chipped, little rust , , , , , Poor			SS VVC	ss3220	2003-1218
	2.50 X-339	Medical Side Table wood 21"w x 16.5"d x 35.5"h, 1 drawer with lock/no key, 1 cupboard, 4 casters , , , , , Poor			SS VVC	ss3357	2003-1218
	6.25 X-342	Table (side table) wood & metal 20"w x 18"d x 32.5"h, drawer, 2 shelves, 1 door, 4 casters, worn & scratched , , , , , Fair			SS VVC	ss3225	2003-1218

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
	10.75 X-422	Table wood 36" x 24" x 29", with center drawer , , , , , Fair			SaskSurplus	7-125	2005-105
	1.50 X-343	Table wood & laminate trapezoid, 58.5"w x 26"d x 30"h , , , , , Fair			SS VVC	ss3347	2003-1218
	1.50 X-344	Table wood & laminate trapezoid, 69.25"w x 26.5"d x 33.75"h , , , , , Fair			SS VVC	ss3346	2003-1218
	30.00 X-345	Tables Lot of 2 (side tables) wood 18"w x 18"d x 22.25"h, white , , , , , Good			SS VVC	ss3239	2003-1218
WD	19.50 X-415	Tire and Steel Rim P225/60R/16, Goodyear Integrity may fit a 2008 Chev. Impala , , , , , Fair		316,232	CVA	ss3332	2004-088
	42.21 X-103	Tires Set of 4 15 inch 195/60R15, SUMITOMO HTR Enhance M/X , , , , , Poor			CVA	SS1792	2003-1215
	42.21 X-104	Tires Set of 4 15 inch 195/60R15, Winter Claw EXT MX , , , , , Poor			CVA	SS1791	2003-1215
WD	80.00 X-105	Tires Set of 4 15 inch 195/65R15, Arctic Claw Winter M + S , , , , , Good			CVA	SS1793	2003-1215
	No Bid X-106	Tires Set of 4 15 inch 215/70R15 Matrix Tour RS , , , , , Poor			CVA	SS1773	2003-1215
WD	80.00 X-107	Tires Set of 4 15 inch, 195/60R15, Firestone FR710 M + S , , , , , Good			CVA	SS1778	2003-1215
	196.66 X-108	Tires Set of 4 15 inch, 215/70R/15, Firestone FR710 M + S , , , , , Good			CVA	SS1790	2003-1215
WD	67.21 X-109	Tires Set of 4 16 inch 205/60R16, Arctic Claw Winter M + S , , , , , Fair			CVA	SS1789	2003-1215
	167.89 X-110	Tires Set of 4 16 inch 205/60R16, Firestone FR710 M + S , , , , , Fair			CVA	SS1775	2003-1215
	181.25 X-111	Tires Set of 4 16 inch 215/65R16, SUMITOMO HTR Enhance M/X , , , , , Good			CVA	SS1795	2003-1215
	216.84 X-112	Tires Set of 4 16 inch 225/60R16, Firestone FR710 M + S , , , , , Good			CVA	SS21774	2003-1215
	42.21 X-113	Tires Set of 4 16 inch 225/60R16, Good Year All season M + S , , , , , Poor			CVA	SS1772	2003-1215
	208.96 X-114	Tires Set of 4 16 inch 225/65R16, Firestone All Season , , , , , Fair			CVA	SS1794	2003-1215

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>WD</b>	<b>77.21</b>	<b>X-115</b>	Tires Set of 4 16 inch, 205/60R16, Firestone FR710 M + S , , , , , Fair		CVA	SS1776	2003-1215
	<b>No Bid</b>	<b>X-116</b>	Tires Set of 4 16 inch, 205/60R16, Matrix Tour RS , , , , , Poor		CVA	SS1777	2003-1215
	<b>127.27</b>	<b>X-117</b>	Tires Set of 4 16 inch, 215/60R/16, SUMITOMO HTR Enhance M/X , , , , , Fair		CVA	SS1780	2003-1215
	<b>No Bid</b>	<b>X-118</b>	Tires Set of 4 16 inch, 215/65R/16, Matrix Tour RS , , , , , Poor		CVA	SS1783	2003-1215
	<b>150.00</b>	<b>X-119</b>	Tires Set of 4 16 inch, 225/60R/16, Winter Claw EXT MX , , , , , Poor		CVA	SS1779	2003-1215
<b>WD</b>	<b>77.21</b>	<b>X-120</b>	Tires Set of 4 16 inch, 225/60R16, SUMITOMO HTR Enhance M/X , , , , , Fair		CVA	SS1781	2003-1215
<b>WD</b>	<b>77.21</b>	<b>X-121</b>	Tires Set of 4 16 inch, P225/60R/16, Firestone FR710 M + S , , , , , Fair		CVA	SS1785	2003-1215
	<b>54.21</b>	<b>X-122</b>	Tires Set of 4 17 inch, 215/60R/17, SUMITOMO HTR Enhance M/X , , , , , Poor		CVA	SS1784	2003-1215
	<b>No Bid</b>	<b>X-123</b>	Tires Set of 4 17 inch, 215/60R/17, Firestone FR710 M + S , , , , , Poor		CVA	SS1786	2003-1215
<b>WD</b>	<b>64.21</b>	<b>X-124</b>	Tires Set of 4 17 inch, 215/60R17, Firestone FR710 M + S , , , , , Fair		CVA	SS1782	2003-1215
<b>WD</b>	<b>105.51</b>	<b>X-125</b>	Tires Set of 4 17 inch, 225/55R/17, Arctic Claw Winter M + S , , , , , Fair		CVA	SS1787	2003-1215
	<b>211.00</b>	<b>X-126</b>	Tires Set of 4 17 inch, 225/60R/17, Firestone FR710 M + S , , , , , Good		CVA	SS1788	2003-1215
<b>WD</b>	<b>86.21</b>	<b>* 12-121</b>	Tires Set of 4 17 inch, 225/55R/17, Goodyear Assurance , , , , , Good		CVA	ss295	1911-957
<b>WD</b>	<b>41.21</b>	<b>* 12-118</b>	Tires Set of 4 16 inch, 225/60R/16, Winter Claw Extreme Grip , , , , , Fair		CVA	ss2285	1911-957
<b>WD</b>	<b>86.21</b>	<b>* 12-127</b>	Tires Set of 4 17 inch, P215/60R/17, Firestone FR710 , , , , , Fair		CVA	ss2293	1911-957
<b>WD</b>	<b>54.21</b>	<b>* 12-119</b>	Tires Set of 4 17 inch, 215/60R/17, Cooper GS4 Touring , , , , , Fair		CVA	ss2290	1911-957
<b>WD</b>	<b>54.21</b>	<b>* 12-120</b>	Tires Set of 4 17 inch, 215/60R/17, Extreme Grip MX Winter Claw , , , , , Fair		CVA	ss2294	1911-957

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
WD	132.51 * 12-115	Tires Set of 4 16 inch, 225/60R/16, Sumitomo Ice Edge , , , , , Good			CVA	ss2287	1911-957
WD	132.51 * 12-116	Tires Set of 4 16 inch, 225/60R/16, Sumitomo Ice Edge , , , , , Good			CVA	ss2281	1911-957
WD	54.21 * 12-113	Tires Set of 4 16 inch, 215/65R/16, Matrix Tour RS Multi Mile , , , , , Fair			CVA	ss2284	1911-957
	125.00 X-437	Tires set of 4 Firestone FR710 M+S P215/70R/15 , , , , , Fair			CVA	SS2280	2006-121
WD	54.21 * 12-123	Tires Set of 4 17 inch, 225/60R/17, Dunlap Grandtrek SJ6 M+S , , , , , Fair			CVA	ss2296	1911-957
	205.00 * 12-124	Tires Set of 4 17 inch, 235/55R/17, Goodyear Ultra Winter Grip , , , , , Good			CVA	ss2288	1911-957
WD	81.21 * 12-111	Tires Set of 4 16 inch, 205/60R/16, Extreme Grip MX Winter Claw , , , , , Fair			CVA	ss2289	1911-957
WD	132.51 * 12-114	Tires Set of 4 16 inch, 225/60R/16, Artic Claw Winter TSI M+S, Goodyear , , , , , Good			CVA	ss2291	1911-957
No Bid	X-346	Toaster Black & Decker, model: T2101C dirty & rusted , , , , , Poor			SS VVC	ss3231	2003-1218
	2.00 X-347	Trash Cans Lot of 4 mesh waste basket, metal small cracks & chips, small rust spots , , , , , Poor			SS VVC	ss3267	2003-1218
	11.00 X-348	Trash Cans & Mat Lot of 4 metal & plastic miscellaneous selection , , , , , Poor			SS VVC	ss3273	2003-1218
No Bid	X-416	Truck Topper Range Rider, fiberglass, to fit a 8 foot box Removed from a 2016 Ram 3500. 6 holes in roof & rear window is loose inside topper. , , , , , Broken Repairable			CVA	ss3335	2004-090
	50.00 X-349	Utility Cart metal 24"w x 18"d x 26.25"h, 4 casters, 2 plugins, long extension , , , , , Poor			SS VVC	ss3393	2003-1218
No Bid	X-350	Vacuum Bissell lift off, model: v91820 120 volts, 60 VHz, 10a, red, looks dirty, unknown if operational , , , , , Poor		14358101E	SS VVC	ss3315	2003-1218
No Bid	X-127	Vehicle Seat vehicle Type Unknown Middle Row Seating with cup holders , , , , , Fair			CVA	SS2415	2003-1215
	1.25 X-352	Wall Art Lot of 2 wood backing, geometric wall décor 11.75"w x 11.75"l , , , , , Fair			SS VVC	ss3290	2003-1218
	101.00 X-208	Armoire wood, tall 3 drawers, 1 hanging rod, 24"d x 33"w x 79"h, locks with no keys , , , , , Fair			SS VVC	ss3326	2003-1218

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
101.00 X-209	Armoire wood, tall 3 drawers, 1 hanging rod, 24"d x 33"w x 79"h, locks with no keys , , , , , Fair			SS VVC	ss3327	2003-1218
101.00 X-210	Armoire wood, tall 3 drawers, 1 hanging rod, 24"d x 33"w x 79"h, locks with no keys , , , , , Fair			SS VVC	ss3328	2003-1218
15.25 X-211	Armoire wood, tall 54.5"w x 23.25"d x 77.75"h, 4 adjustable shelves, 2 locks no keys, 1 hanging rod, mint, scuffed , , , , , Poor			SS VVC	ss3372	2003-1218
No Bid X-132	Battery EMC 2, PN-078-000-086 Large battery, No hard drives. Unsure if operational however brand new in box. (HEAVY) , , , , , Fair		AC121120200367	CS ITD	S17 (No Tag)	2002-1190
3.50 X-212	Binders Lot of 2 boxes approximately 33 binders, variety of colours, 3 rings, variety of 1-3" , , , , , Fair			SS VVC	ss3245	2003-1218
5.00 X-213	Binders Lot of 2 boxes approximately 44 binders, variety of colours, 3 rings, variety of 1-3" , , , , , Fair			SS VVC	ss3244	2003-1218
8.92 X-214	Binders Lot of 1 box approximately 15 binders, 1-3", 3 rings, variety of colours , , , , , Fair			SS VVC	ss3255	2003-1218
5.86 X-215	Binders Lot of 1 box approximately 17 binders, 1-3", 3 rings, variety of colours , , , , , Fair			SS VVC	ss3259	2003-1218
4.00 X-216	Binders Lot of 2 boxes approximately 37 binders, 1-3", 3 rings, variety of colours , , , , , Fair			SS VVC	ss3258	2003-1218
1.25 X-217	Blinds Mainstays vinyl 39.5"w x 64"l, white , , , , , New - Unused			SS VVC	ss3306	2003-1218
7.50 X-401	Bookcase metal frame 36"w x 14"d x 30"h, wood grain laminate, sliding doors, adjustable shelves , , , , , Fair			LRWS	CDP 29542 ss3208	2002-1195
7.50 X-198	Bookcase Metal, Laminate Top 2 sliding doors, 1 shelf 42x14x36 , , , , ,			AG	CDP29238 SS3307a	2002-1139
7.50 X-199	Bookcase Metal, Laminate Top 2 sliding doors, 1 shelf 42x14x36 , , , , ,			AG	CDP29238 SS3307b	2002-1139
11.75 X-218	Bookcase wide, wood 4 adjustable shelves, 72"w x 24"d x 41"h, finish worn, top small stains , , , , , Poor			SS VVC	ss3282	2003-1218
11.00 X-219	Bookcase wide, wood 43"w x 16"d x 47.75"h, 2 adjustable shelves , , , , , Fair			SS VVC	ss3387	2003-1218
11.75 X-220	Bookcase wide, wood 72"w x 24"d x 41.5"h, 6 adjustable shelves, laminate top, stained, finish worn, chipped , , , , , Poor			SS VVC	ss3281	2003-1218

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-221	Books Lot of 3 boxes miscellaneous pharmaceutical selection All books published between the early 1970s & late 1990s. , , , , Fair			SS VVC	ss3293	2003-1218
10.75	X-222	Cabinet for cards, wood 19.5"w x 17.5"d x 15.25"h, 4 drawers, 4 locks with no keys, upper right drawer locked/doesn't open, worn & scratched , , , , Poor			SS VVC	ss3237	2003-1218
8.50	X-200	Cabinet Laminate wood Pepperdust, 4 shelves, missing handle, 36x18x38.35 , , , , Broken Repairable			AG	CDP29246 SS3308	2002-1139
5.50	X-223	Cabinet short, wood no shelves, 2 cupboards, no doors, 60"w x 24.25"d x 31.3"h, laminate top, worn/scuffed on edges , , , , Poor			SS VVC	ss3278	2003-1218
111.00	X-224	Cabinet storage with glass displays 34.25"w x 12"d x 50.25"h, 3 shelves, scratched, chipped, scuffed , , , , Fair			SS VVC	ss3262	2003-1218
5.50	X-225	Cabinet storage, wood 3 shelves, 48"w x 20.25"d x 47.5"h, 4 caster, worn , , , , Poor			SS VVC	ss3344	2003-1218
40.00	X-227	Cabinet wide, wood 72.5"w x 31.5"d x 35.75"h, green, laminate top, 4 doors on both sides, 2 shelves, 8 drawers, worn, discolored , , , , Fair			SS VVC	ss3283	2003-1218
*MT	X-228	Cabinet wood 36"w x 16"d x 72.5"h, 4 adjustable shelves, magnet closure, grey , , , , Fair			SS VVC	ss3373	2003-1218
21.25	X-229	Cabinet wood 66.25"w x 16.25"d x 72.25"h, 19 adjustable shelves, white, worn, small chips , , , , Poor			SS VVC	ss3371	2003-1218
3.50	X-230	Cabinet wood 67.25"w x 20.25"d x 36.25"h, 2 drawers, 2 doors , , , , Poor			SS VVC	ss3297	2003-1218
3.50	X-231	Cabinet wood 2 cupboards, 4 doors, no shelves, 59.70"w x 28.75"d x 30.25"h, chipped, light pink , , , , Poor			SS VVC	ss3279	2003-1218
19.75	X-232	Cabinet wood 30"w x 12.5"d x 50.25"h, 3 adjustable shelves , , , , Poor			SS VVC	ss3299	2003-1218
26.00	X-234	Cabinet wood 36"w x 14"d x 46"h, 5 shelves, 2 drawers, 4 doors with locks & no keys , , , , Fair			SS VVC	ss3280	2003-1218
45.75	X-235	Cabinet wood with glass door display 120.5"w x 15.25"d x 60.5"h, 5 drawers, 5 sliding door, worn & slightly chipped at bottom, small scratches & dents on sides , , , , Fair			SS VVC	X-V285	2003-1218
3.50	X-236	Cabinet wood, laminate 4 casters, blue & white, 2 doors, 2 shelves, 23.75"d x 37.75"w x 35.5"h , , , , Fair			SS VVC	ss3325	2003-1218

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1.00 X-237	Cabinet wood 36"w x 20"d x 41"h, badly scuffed , , , , , Poor			SS VVC	ss3324	2003-1218
1.00 X-238	Card Holder metal 12.25"w x 16"d x 5.5"h, 2 drawers , , , , , Fair			SS VVC	ss3246	2003-1218
3.00 X-239	Card Holder wood 2 drawers, 7.25"w x 18"d x 10.5"h , , , , , Fair			SS VVC	ss3314	2003-1218
6.60 X-251	Chair ergonomic 5 casters, adjustable, arms, blue , , , , , Fair			SS VVC	ss3320	2003-1218
4.80 X-252	Chair ergonomic 5 casters, adjustable, arms, grey , , , , , Fair			SS VVC	ss3321	2003-1218
2.60 X-253	Chair ergonomic 5 casters, arms, red , , , , , Fair			SS VVC	ss3319	2003-1218
8.75 X-201	Chair Lot of 5 Ergonomic, 5 caster, armrest, adjustable Grey Fabric , , , , , Fair			AG	CDP29242 SS3309	2002-1139
No Bid X-258	Chair (side chair) metal & fabric light pink, dirty , , , , , Fair			SS VVC	ss3322	2003-1218
No Bid X-259	Chair (side chair) wood wood & fabric are worn , , , , , Fair			SS VVC	ss3342	2003-1218
No Bid X-260	Chair (side chair) wood worn on edges , , , , , Fair			SS VVC	ss3323	2003-1218
No Bid X-261	Chair (side chair) wood & fabric dusty rose, fabric worn , , , , , Fair			SS VVC	ss3348	2003-1218
No Bid X-262	Chair (side chair) wood & fabric red, small stains , , , , , Fair			SS VVC	ss3216	2003-1218
No Bid X-263	Chair (side chair) wood & fabric rose, fabric worn , , , , , Fair			SS VVC	ss3349	2003-1218
7.70 X-428	Chair swivel, tilter (for conference rooms) armrests, 5 casters, grey fabric , , , , , Fair			SaskSurp lus	SS3453	2006-113
15.51 X-429	Chair swivel, tilter (for conference rooms) armrests, 5 casters, brown circle patterned fabric , , , , , Fair			SaskSurp lus	SS3451	2006-113
5.60 X-430	Chair swivel, tilter (for conference rooms) armrests, 5 casters, light grey fabric , , , , , Fair			SaskSurp lus	SS3452	2006-113
No Bid X-264	Chairs Lot of 2 (side chair) wood & fabric, worn , , , , , Fair			SS VVC	ss3341	2003-1218
8.50 X-402	Chairs Lot of 3 (side chair) wood frame, brown fabric covered, arm rests , , , , , Fair			LRWS	CDP 29534 ss3445	2002-1195
No Bid X-265	Chairs Lot of 2 (side chairs) metal & grey fabric, worn , , , , , Good			SS VVC	ss3352	2003-1218
36.00 X-266	Chairs Lot of 6 (side chairs) metal & vinyl, worn at the seams, holes , , , , , Poor			SS VVC	ss3351	2003-1218



	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-267	Chairs Lot of 2 (side chairs) wood & beige fabric, worn , , , , , Fair			SS VVC	ss3354	2003-1218
No Bid	X-268	Chairs Lot of 2 (side chairs) wood & fabric grey stripes, wood is worn , , , , , Poor			SS VVC	ss3355	2003-1218
15.00	X-269	Chairs Lot of 3 (side chairs) wood & fabric grey, fabric is worn, stained & dirty , , , , , Fair			SS VVC	ss3353	2003-1218
No Bid	X-403	Chairs Lot of 4 swivel, wood frame, fabric covered 4 castors, arm rests, brown , , , , , Fair			LRWS	CDP 29534 ss3209	2002-1195
21.50	X-423	Chairs Lot of 5 (for reception area) metal frame, fabric covered armrests, blue , , , , , Good			SS VVC	SS3449	2006-112
5.63	X-424	Coat Rack wood 61.5" tall, 4 double prongs, marker on side, holes from pre-existing hooks , , , , , Poor			SS VVC	SS3447	2006-112
No Bid	X-133	Control Engine Cisco ACE 4710, PN-QR2700 Small control engine, hard drives have been removed. Unsure if operational , , , , , Fair		QCF14050358	CS ITD	S7 (No Tag)	2002-1190
No Bid	X-134	Control Engine Cisco ACE 4710, PN-QR2700 Small control engine, hard drives have been removed. Unsure if operational , , , , , Fair		SN-Unkown rubbed off	CS ITD	S11 (454731)	2002-1190
*MT	X-205	Desk Laminated Wood 72"W x 36"D x 29 1/2"H, taupe, four drawers. , , , , , Good			AG	1 CDP29315/ SS3213	2002-1140
40.00	X-273	Desk wood 36.25"w x 24.25"d x 31"h, 1 drawer, worn on the top , , , , , Fair			SS VVC	ss3298	2003-1218
40.00	X-274	Desk wood 4 drawers, 30.25"d x 42.25"w x 30.5"h, lock no key , , , , , Poor			SS VVC	ss3247	2003-1218
No Bid	X-149	Drive Library Compaq-Drive Library, PN-212752090001 All hard drives have been removed, unsure if operational. , , , , , Fair		C83600024K90229	CS ITD	(S11) 469172	2002-1192
11.27	X-150	Drive Library IBM, PN-7383-AC10 All hard drives have been removed, unsure if operational. , , , , , Fair		6GYWH5	CS ITD	(S25) No GoS Tag	2002-1192
9.00	X-202	Filing Cabinet Lateral, 4 drawer 36x18x52, Beige, no key , , , , , Fair			AG	CDP29241 SS3310	2002-1139
2.00	X-404	Filing Cabinet Lateral, 4 drawer 36"w x 18"d x 51"h, bar in back bent, no key, beige , , , , , Broken Repairable			LRWS	CDP 29540 ss3207	2002-1195
25.27	X-405	Filing Cabinet Vertical, 4 drawer 18"w x 28"d x 51"h, no keys, beige , , , , , Fair			LRWS	CDP 29535 SS3444	2002-1195



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
20.00 X-280	Filing Cabinet Lateral, 3 drawer 36"w x 19.25"d x 41"h, lock with no key , , , , , Fair			SS VVC	ss3376	2003-1218
20.00 X-281	Filing Cabinet Lateral, 3 drawer 36"w x 19.25"d x 41"h, lock with no key , , , , , Fair			SS VVC	ss3385	2003-1218
25.00 X-282	Filing Cabinet Lateral, 4 drawer 36"w x 18"d x 51.5"h, lock with no key , , , , , Fair			SS VVC	ss3384	2003-1218
25.00 X-283	Filing Cabinet Lateral, 4 drawer 36"w x 18"d x 51.5"h, lock with no key , , , , , Fair			SS VVC	ss3386	2003-1218
25.00 X-284	Filing Cabinet Lateral, 4 drawer 36"w x 18"d x 51.5"h, lock with no key , , , , , Fair			SS VVC	ss3388	2003-1218
4.50 X-285	Filing Cabinet Lateral, 4 drawer 36"w x 18"d x 53"h, lock with no key , , , , , Fair			SS VVC	ss3383	2003-1218
6.50 X-286	Filing Cabinet Lateral, 4 drawer 36.25"w x 18"d x 70"h, lock with no key , , , , , Fair			SS VVC	ss3382	2003-1218
8.50 X-287	Filing Cabinet Lateral, 4 drawer 36.25"w x 18.25"d x 52"h, lock with key , , , , , Fair			SS VVC	ss3377	2003-1218
16.75 X-290	Filing Cabinet Lateral, 5 drawer 36.75"w x 20"d x 63.75"h, lock with key , , , , , Fair			SS VVC	ss3389	2003-1218
15.50 X-291	Filing Cabinet Lateral, 5 drawer 36.75"w x 20"d x 63.75"h, lock with no key , , , , , Fair			SS VVC	ss3379	2003-1218
18.50 X-292	Filing Cabinet Lateral, 5 drawer 36.75"w x 20"d x 63.75"h, lock with no key , , , , , Fair			SS VVC	ss3380	2003-1218
17.00 X-293	Filing Cabinet Lateral, 5 drawer 36.75"w x 20"d x 63.75"h, lock with no key , , , , , Fair			SS VVC	ss3381	2003-1218
25.27 X-294	Filing Cabinet Vertical, 4 drawer 18.25"w x 28"d x 51.25"h, lock with no key , button mechanism to open , , , , , Fair			SS VVC	ss3378	2003-1218
No Bid X-135	Firewall Barracuda Spam Firewall 400 Small sized firewall, hard drives have been removed. Unsure if operational , , , , , Fair		125,045	CS ITD	S13 (No Tag)	2002-1190
14.09 X-301	Keyboard Dell, model: KB216p wired , , , , , New - Unused		CN-0N6R8GPRC00-87D09DS	SS VVC	ss3272	2003-1218
14.09 X-302	Keyboard Lenovo, model: KB1021 wired , , , , , New - Unused		0003816	SS VVC	ss3271	2003-1218

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1.75 X-303	Keyboard Lenovo keyboard, model: KU-0225 wired , , , , , Fair		1662888	SS VVC	ss3263	2003-1218
2.00 X-304	Letter Trays Lot of 10 plastic, black , , , , , Fair			SS VVC	ss3294	2003-1218
No Bid X-136	Media Server Cisco MCS 7800, PN-AH771A Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		MX292200BZ	CS ITD	S1 (466912)	2002-1190
No Bid X-137	Media Server Cisco MCS 7800, PN-AH771A Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		MX292200DR	CS ITD	S2 (466914)	2002-1190
No Bid X-138	Media Server Cisco MCS 7800, PN-AH771A Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		MX29220079	CS ITD	S3 (466913)	2002-1190
No Bid X-139	Media Server Cisco MCS 7800, PN-AH771A Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		2UX917029E	CS ITD	S6 (466916)	2002-1190
11.27 X-140	Multilayer Director Cisco Systems DS-C9509, PN-COM5A00ARA Medium sized mulitylayer director , hard drives have been removed. Unsure if operational (HEAVY) , , , , , Fair		DCH10081261	CS ITD	S15 (406920)	2002-1190
11.27 X-141	Multilayer Director Cisco Systems DS-C9509, PN-COM5A00ARA Medium sized mulitylayer director , hard drives have been removed. Unsure if operational (HEAVY) , , , , , Fair		DCH10382029	CS ITD	S16 (406921)	2002-1190
4.50 X-311	Office/Desk Supplies Lot of 3 items pencil sharpener, new tape dispenser, used box of letter sized file folders (61 remaining) , , , , , Good			SS VVC	ss3305	2003-1218
12.25 X-206	Partition Metal and Fabric 61"W x 2"D x 48"H, chrome frame and legs, beige fabric , , , , , Excellent			AG	3 CDP29317/ SS3214	2002-1140
No Bid X-326	Printer Cartridge model: 10117-00 Basic Laser cartridge compatible to HP 1338A, for HP LaserJet 42001/4200N1/4200TN/4200DTN/4200DTNS/4200DTNSL , , , , , New - Unused			SS VVC	ss3270	2003-1218
No Bid X-142	Server Cisco MCS 7800, PN-AH771A Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		2UX9170292	CS ITD	S8 (No Tag)	2002-1190

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-143	Server Cisco MCS 7800 Server, PN-4251-AC1		KQ888CX	CS ITD	S4 (No Tag)	2002-1190
No Bid	X-144	Server Cisco MCS 7800 Server, PN-4251-AC1		KQ931BR	CS ITD	S5 (No Tag)	2002-1190
No Bid	X-151	Server Compaq ProLiant CL1600R, PN-512-123-US Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		D942CNK1K516	CS ITD	(S30) 454781	2002-1192
No Bid	X-152	Server Compaq ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		D319FRW1H001	CS ITD	(S13) 454770	2002-1192
No Bid	X-153	Server Compaq ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		D334LJC1H124	CS ITD	(S19) 454777	2002-1192
No Bid	X-145	Server Compaq ProLiant ML530, PN-271246-001 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		D043FPW1K051	CS ITD	S14 (414430)	2002-1190
No Bid	X-154	Server Compaq ProLiant ML530, PN-271246-001 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		3882Q024	CS ITD	(S33) 454773	2002-1192
No Bid	X-146	Server Dell Power Edge 2600, PN-SCL Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		56LTG31	CS ITD	S9 (406914)	2002-1190
No Bid	X-155	Server Dell Power Edge 2650, PN-SMP01 Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		4MCDD61	CS ITD	(S2) 466900	2002-1192
No Bid	X-156	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		ESX32P	CS ITD	(S1) 417995	2002-1192
No Bid	X-157	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		FZPBTJ1	CS ITD	(S7) 420222	2002-1192
No Bid	X-158	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational. , , , , , Fair		BQVMNM1	CS ITD	(S8) 468838	2002-1192

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-159	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		BQTPNM1	CS ITD	(S17) 468837	2002-1192
No Bid	X-160	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		ESX33P	CS ITD	(S18) 417997	2002-1192
No Bid	X-161	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		9ZPBTJ1	CS ITD	(S21) 420221	2002-1192
No Bid	X-162	Server Dell Power Edge R710, PN-E02S001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		BQVNNM1	CS ITD	(S26) 468836	2002-1192
No Bid	X-163	Server Dell PowerEdge 1850, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		BKFDS51	CS ITD	(S16) 418476	2002-1192
No Bid	X-168	Server Dell PowerEdge 1850, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		6GP74C1	CS ITD	(S39) 414416	2002-1192
No Bid	X-164	Server Dell PowerEdge 1855, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		DCGBB71	CS ITD	(S35) No Gos Tag	2002-1192
No Bid	X-165	Server Dell PowerEdge 1855, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		BG11S91	CS ITD	(S36) No Gos Tag	2002-1192
No Bid	X-166	Server Dell PowerEdge 1855, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		5H11S91	CS ITD	(S37) No Gos Tag	2002-1192
No Bid	X-167	Server Dell PowerEdge 1955, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		8GP74C1	CS ITD	(S38) 414417	2002-1192
No Bid	X-169	Server Dell PowerEdge 1955, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		1HP74C1	CS ITD	(S40) 414420	2002-1192
No Bid	X-170	Server Dell PowerEdge 1955, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		GGP74C1	CS ITD	(S41) No GoS Tag	2002-1192
No Bid	X-171	Server Dell PowerEdge 1955, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		2FP74C1	CS ITD	(S42) 414419	2002-1192
No Bid	X-173	Server Dell PowerEdge 1955, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		BCP74C1	CS ITD	(S44) 414418	2002-1192

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-172	Server Dell PowerEdge 1955, PN-EMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		BDP74C1	CS ITD	(S43) 414414	2002-1192
No Bid	X-174	Server Dell PowerEdge 2850, PN-EMS Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		D7Y6Z61	CS ITD	(S9) 414443	2002-1192
No Bid	X-175	Server Dell PowerEdge 2950, PN-EMS01 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		BZT8DG1	CS ITD	(S6) 412055	2002-1192
No Bid	X-147	Server Dell PowerEdge 2950, PN-EMS01 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		D4RSTF1	CS ITD	S12 (444518)	2002-1190
No Bid	X-176	Server Fujitsu Primergy RX200 S7, PN-RX200HI-D3032 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		YLAQ017527	CS ITD	(S29) No GoS Tag	2002-1192
No Bid	X-177	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		2UX60101HL	CS ITD	(S3) 454780	2002-1192
No Bid	X-178	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		D334LJC1H194	CS ITD	(S4) 454779	2002-1192
No Bid	X-179	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		2UX601018X	CS ITD	(S5) 454785	2002-1192
No Bid	X-180	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		D334LJC1H195	CS ITD	(S10) 454760	2002-1192
No Bid	X-181	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		D319FRW1H000	CS ITD	(S20) 454771	2002-1192
No Bid	X-182	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		2UX60101ED	CS ITD	(S22) 454784	2002-1192

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-183	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		2UX60101BV	CS ITD	(S23) 454774	2002-1192
No Bid	X-184	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		D334LJC1H122	CS ITD	(S24) 454778	2002-1192
No Bid	X-185	Server HP ProLiant DL380, PN-378735-001 Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		2UX60101HK	CS ITD	(S28) 454775	2002-1192
No Bid	X-186	Server HP ProLiant ML530, PN-271246-001 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		D334LP94H020	CS ITD	(S32) 454762	2002-1192
No Bid	X-187	Server HP ProLiant ML530, PN-271246-001 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		D334LP94H017	CS ITD	(S34) 454761	2002-1192
2.00	X-188	Server IBM Power PC RISC System-6000 F50, PN-7025 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		S70251019137	CS ITD	(S45) No Gos Tag	2002-1192
No Bid	X-189	Server IBM Power PC RISC System-6000 F50, PN-7025 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		S70251033218	CS ITD	(S46) No Gos Tag	2002-1192
2.00	X-190	Server IBM Power PC RISC System-6000 F50, PN-7025 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		S70251024670	CS ITD	(S47) No Gos Tag	2002-1192
1.50	X-191	Server IBM Power PC RISC System-6000 F50, PN-7025 Medium sized server, hard drives have been removed. Unsure if operational. , , , , , Fair		S70251014764	CS ITD	(S48) No Gos Tag	2002-1192
No Bid	X-192	Server IBM XSERIES 346, PN-8840-35U Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		KQAYX8P	CS ITD	(S12) 410841	2002-1192
No Bid	X-193	Server IBM XSERIES 346, PN-8840-35U Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		KPPTK10	CS ITD	(S14) 401092	2002-1192
No Bid	X-194	Server IBM XSERIES 346, PN-8840-35U Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		KPPZM79	CS ITD	(S15) 401270	2002-1192
No Bid	X-195	Server IBM XSERIES 346, PN-8840-35U Small sized storage server, hard drives have been removed. Unsure if operational , , , , , Fair		KPPTH69	CS ITD	(S27) 401271	2002-1192

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-196	Server Library Dell, PN-BMX All harddrives have been removed, unsure if operational. , , , , Fair		9CGBB71	CS ITD	(S31) 406903	2002-1192
15.75	X-332	Storage Cabinet tall, wood 40.5"w x 20"d x 50.5"h, 2 doors, 3 shelves, 4 casters, white , , , , Fair			SS VVC	ss3223	2003-1218
15.75	X-333	Storage Cabinet tall, wood 40.5"w x 20"d x 50.5"h, 2 doors, 3 shelves, lock, no key, hooks on the bottom, 4 casters, pink , , , , Fair			SS VVC	ss3224	2003-1218
52.00	X-334	Storage Cabinet tall, wood 7 shelves, 2 sliding doors, 60.75"w x 15.25"d x 54.25"h , , , , Fair			SS VVC	ss3277	2003-1218
No Bid	X-148	Storage Server Dell Power Vault 745N, PN-SMU Small sized storage server, hard drives have been removed. Unsure if operational , , , , Fair		6F4KW61	CS ITD	S10 (No Tag)	2002-1190
No Bid	X-431	Table metal 60.25"w x 20"d x 30"h, chrome legs, arborite top brown wood grain , , , , Fair			SaskSurplus	SS2977	2006-113
21.51	X-406	Table pepperdust 60"w x 30"d x 30"h , , , , Good			LRWS	CDP 29539 ss3212	2002-1195
12.00	X-407	Table round, pepperdust 48" diameter , , , , Good			LRWS	CDP 29538 ss3211	2002-1195
3.00	X-408	Table/Desk metal frame 36"w x 24"d x 29"h, wood grain laminate , , , , Fair			LRWS	CDP 29357 ss3210	2002-1195
3.25	X-340	Table/Printer Stand wood 27"w x 23.75"d x 32"h, grey, 2 pull out shelves, 4 casters , , , , Good			SS VVC	ss3356	2003-1218
3.00	X-341	Table/Printer Stand wood 27.5"w x 23.25"d x 32"h, 2 pull out trays, 4 casters , , , , Good			SS VVC	ss3303	2003-1218
1.01 *	11-823	Pumper Trailer Wood Frame and tires are good condition, wood top is rotting. , , , , Poor		FCT-018, Invalid VIN	SPSA	11	1911-944
1,551.00	X-503	ATV 1995 Honda Fourtrax Red color, runs good, has working winch. Plastic body damage, brakes require maintenance/replacement. , , , , Poor		E15285A706394TRX30	ENV	2	2003-1216
366.00	X-504	Snowmobile 1994 Polaris Indy Touring Blue color, non-operational, needs spark plug coil. Carbs cleaned recently. , , , , Broken Repairable		2,472,392	ENV	1	2003-1216
1.60	X-564	Map Colour Topographical 62l-Melville, topographical 1990, located in Hudson Bay , , , , New - Unused			ENV	45 62L	2004-010



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
11.11 X-558	Map Colour Topographical 62m-Yorkton, topographical 1974, located in Hudson Bay , , , , New - Unused			ENV	39 62M	2004-010
11.11 X-557	Map Colour Topographical 62n-Duck Mountain, topographical 1972, located in Hudson Bay , , , , New - Unused			ENV	38 62N	2004-010
1.60 X-523	Map Colour Topographical 63-c - Swan Lake, topographical 1976, located in Hudson Bay , , , , New - Unused			ENV	4 63C	2004-010
1.60 X-568	Map Colour Topographical 63c12-Armit Lake, topographical 1976, located in Hudson Bay , , , , New - Unused			ENV	49 63C12	2004-010
1.60 X-569	Map Colour Topographical 63c13-Roscoe, topographical 1976, located in Hudson Bay , , , , New - Unused			ENV	50 63C13	2004-010
1.60 X-575	Map Colour Topographical 63c4-Thunder Hill, topographical 1992, located in Hudson Bay , , , , New - Unused			ENV	56 63C4	2004-010
1.60 X-571	Map Colour Topographical 63c5-Townsend Lake, topographical 1976, located in Hudson Bay , , , , New - Unused			ENV	52 63C5	2004-010
1.60 X-522	Map Colour Topographical 63-d - Hudson Bay, topographical 1990, located in Hudson Bay , , , , New - Unused			ENV	3 63D	2004-010
1.60 X-533	Map Colour Topographical 63-d10-Weekes, topographical 2009, located in Hudson Bay , , , , New - Unused			ENV	14 63D10	2004-010
11.11 X-534	Map Colour Topographical 63-d11-Porcupine Plain, topographical 1993, located in Hudson Bay , , , , New - Unused			ENV	15 63D11	2004-010
15.11 X-535	Map Colour Topographical 63d12-Bjorkdale, topographical 1993, located in Hudson Bay , , , , New - Unused			ENV	16 63D12	2004-010
11.11 X-536	Map Colour Topographical 63d13-Crooked River, topographical 1993, located in Hudson Bay , , , , New - Unused			ENV	17 63D13	2004-010
5.22 X-537	Map Colour Topographical 63d14-Mistatim, topographical 1993, located in Hudson Bay , , , , New - Unused			ENV	18 63D14	2004-010
1.60 X-538	Map Colour Topographical 63d15-Prairie River, topographical 2009, located in Hudson Bay , , , , New - Unused			ENV	19 63D15	2004-010
1.60 X-539	Map Colour Topographical 63d16-Hudson Bay, topographical 1992, located in Hudson Bay , , , , New - Unused			ENV	20 63D16	2004-010
5.22 X-524	Map Colour Topographical 63-d1-Swan Plain, topographical 1993, located in Hudson Bay , , , , New - Unused			ENV	5 63D1	2004-010



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5.22 X-525	Map Colour Topographical 63-d2-Endeavour, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	6 63D2	2004-010
5.22 X-526	Map Colour Topographical 63-d3-Lintlaw, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	7 63D3	2004-010
1.60 X-527	Map Colour Topographical 63-d4-Kelvington, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	8 63D4	2004-010
1.60 X-528	Map Colour Topographical 63-d5-Nut Lake, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	9 63D5	2004-010
5.22 X-529	Map Colour Topographical 63-d6-Klogei Lake, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	10 63D6	2004-010
1.60 X-530	Map Colour Topographical 63-d7-Reserve, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	11 63D7	2004-010
5.22 X-531	Map Colour Topographical 63-d8-McBride Lake, topographical 1976, located in Hudson Bay , , , , , New - Unused			ENV	12 63D8	2004-010
5.22 X-532	Map Colour Topographical 63-d9-Pepaw River, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	13 63D9	2004-010
1.60 X-521	Map Colour Topographical 63-e - Pasqua Hills, topographical 1985, located in Hudson Bay , , , , , New - Unused			ENV	2 63E	2004-010
5.00 X-549	Map Colour Topographical 63e10-Sipanok Channel, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	30 63E/10	2004-010
1.60 X-550	Map Colour Topographical 63e11-Tobin Lake, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	31 63E/11	2004-010
1.60 X-551	Map Colour Topographical 63e12-Pemmican Point, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	32 63E/12	2004-010
1.60 X-552	Map Colour Topographical 63e13-Missipuskiow River, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	33 63E/13	2004-010
1.60 X-553	Map Colour Topographical 63e14-New Channel, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	34 63E/14	2004-010
1.60 X-554	Map Colour Topographical 63e15-Old Channel, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	35 63E/15	2004-010
1.60 X-555	Map Colour Topographical 63e16-Cumberland House, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	36 63E/16	2004-010

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
1.60 X-540	Map Colour Topographical 63e1-Leaf Lake, topographical 1984/2009, located in Hudson Bay , , , , , New - Unused			ENV	21 63E/1	2004-010
1.60 X-541	Map Colour Topographical 63e2-Fir River, topographical 1984, located in Hudson Bay , , , , , New - Unused			ENV	22 63E/2	2004-010
5.22 X-542	Map Colour Topographical 63e3-Connell Creek, topographical 1984, located in Hudson Bay , , , , , New - Unused			ENV	23 63E/3	2004-010
5.22 X-543	Map Colour Topographical 63e4-Arborfield, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	24 63E/4	2004-010
5.22 X-544	Map Colour Topographical 63e5-Carrot River, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	25 63E/5	2004-010
1.60 X-545	Map Colour Topographical 63e6-Battle Heights, topographical 1984, located in Hudson Bay , , , , , New - Unused			ENV	26 63E/6	2004-010
1.60 X-546	Map Colour Topographical 63e7-Red Earth, topographical 1984, located in Hudson Bay , , , , , New - Unused			ENV	27 63E/7	2004-010
1.60 X-547	Map Colour Topographical 63e8-Otosquen, topographical 1984, located in Hudson Bay , , , , , New - Unused			ENV	28 63E/8	2004-010
1.60 X-548	Map Colour Topographical 63e9-Mountain Cabin, topographical 1987, located in Hudson Bay , , , , , New - Unused			ENV	29 63E/9	2004-010
1.60 X-520	Map Colour Topographical 63-f - The Pas, topographical 1978, located in Hudson Bay , , , , , New - Unused			ENV	1 63F	2004-010
1.60 X-570	Map Colour Topographical 63f12-Culdesac Lake, topographical 1977, located in Hudson Bay , , , , , New - Unused			ENV	51 63F12	2004-010
1.60 X-572	Map Colour Topographical 63f13-Barrier Lake, topographical 1980, located in Hudson Bay , , , , , New - Unused			ENV	53 63F13	2004-010
1.60 X-574	Map Colour Topographical 63f4-Chemong Creek, topographical 1980, located in Hudson Bay , , , , , New - Unused			ENV	55 63F4	2004-010
1.60 X-573	Map Colour Topographical 63f5-Turnberry, topographical 1980, located in Hudson Bay , , , , , New - Unused			ENV	54 63F5	2004-010
1.60 X-565	Map Colour Topographical 63k-Cormorant Lake, topographical 1986, located in Hudson Bay , , , , , New - Unused			ENV	46 63K	2004-010
1.60 X-561	Map Colour Topographical 63l-Amisk Lake, topographical 1968, located in Hudson Bay , , , , , New - Unused			ENV	42 63L	2004-010

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-562	Map Colour Topographical 63m15-Preeceville, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	43 63M15	2004-010
5.22	X-563	Map Colour Topographical 63m16-Norquay, topographical 1993, located in Hudson Bay , , , , , New - Unused			ENV	44 63M16	2004-010
1.60	X-560	Map Colour Topographical 63m-Pelican Narrows, topographical 1961, located in Hudson Bay , , , , , New - Unused			ENV	41 63M	2004-010
1.60	X-567	Map Colour Topographical 72i-Regina, topographical 1979, located in Hudson Bay , , , , , New - Unused			ENV	48 72I	2004-010
1.60	X-566	Map Colour Topographical 72p-Wynyard, topographical 1980, located in Hudson Bay , , , , , New - Unused			ENV	47 72P	2004-010
5.22	X-556	Map Colour Topographical 73a-Melfort, topographical 1976, located in Hudson Bay , , , , , New - Unused			ENV	37 73A	2004-010
5.00	X-559	Map Colour Topographical 73h-Prince Albert, topographical 1977, located in Hudson Bay , , , , , New - Unused			ENV	40 73H	2004-010

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>LA RONGE, Environment, 1100 Poirier Street.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Brad Johns 306-425-4240, 306-425-0163 or at brad.johns@gov.sk.ca</b>						
1,258.00	X-757	ATV Honda Foreman 300 4 x 4 comes with cargo box , , , , , Fair	48TE2265	ENV	1	2004-078
521.21	X-758	Boat Lund 14ft bent side on bow, hole on side , , , , , Broken Repairable	SK8324	ENV	5/5.1	2004-078
5,166.00	X-759	Boat, Motor and Trailer Lund Alaskan Boat -18ft; Motor - Yamaha 50HP, 01/02; Trailer, 2011 Easy Loader- Sing Axle Trailer , , , , , Fair	1ZEAAKYB2BA013521	ENV	2.1, 2.2, 2.3	2004-078
1,451.00	X-760	Motor Honda 4 stroke 90hp No Gears , , , , , Broken Repairable	2,002,399	ENV	3	2004-078
302.15	X-761	Motor Johnson 20hp , , , , , Poor	SK8320	ENV	4	2004-078
<b>MEADOW LAKE, Highways, #4 305-9TH Street West.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Mark Eisenkirch 306-526-9103, mark.eisenkirch@gov.sk.ca</b>						
WD	879.99 * 7-501	Truck 1995 INTERNATIONAL 2674 Tandem Dump Truck, 2 wheel drive Cummins M11, inline 6 diesel standard 10 speed air, cruise, tilt , Yellow, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: coolant in crankcase, cab has holes rusted through, paint rusty, underside of box very rusty, hasn't been run for 2 years, Will not pass SGI safety>, As is, Where is	13,744 Hrs.	1HTGLAHT5SH649732	HI	D95012 TOW 1906-291 ONLY
WD	203.00 * 7-505	Truck 1990 INTERNATIONAL IHC Single axle, duals, oil distributor, RWD Nissan NE6T 452 cu in, inline 6, diesel 4 speed auto air, tilt, cruise aftermarket A/C, Yellow, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Rust jacking on frame fails a safety inspection, inside right drive tire has large hole in sidewall, inside left drive tire worn badly, Unit is in poor condition>, As is, Where is	193,78 Kms 8,701 Hrs	JPAWUYTN2LNH55125	HI	D90025 TOW 1907-487 ONLY

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>MELVILLE, Agriculture, Saskatchewan Crop Insurance Agency, 484 Prince William Drive.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING.</b>						
<b>For information on items contact Curtis Fleury 639-638-6280, curtis.fleury@scic.ca, or Heather Ames 639-638-6281, heather.ames@scic.ca</b>						
No Bid	X-510	Cabinet Wood Pepperdust, 2 door, 1 shelf 42x13.75x36 , , , , , Good		SCIC	4 29510	2003-1220
No Bid	X-511	Credenza Wood 71x19.5x28.5 , , , , , Good		SCIC	3 29361	2003-1220
*MT	X-512	Desk Wood veneer Modular, 3 piece with hutch , , , , , Good		SCIC	2 29362	2003-1220
No Bid	X-509	Server Racks Lot of 2 Metal with glass door 31 1/2"X31 3/4"X85" , , , , , Good		SCIC	1	2003-1219
20.00	X-513	Storage Cabinet Metal 2 doors, 36x20x72 , , , , , Good		SCIC	1 29363	2003-1220
<b>NORTH BATTLEFORD, Central Services, Property Management, 1 Jersey Street (Sask Hospital)</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Dan Nahirney 306-441-1048, 306-440-4144, or at dan.nahirney@gov.sk.ca</b>						
WD	657.00 X-807	Generator 1985 Onan 75 KW OENT-15R/9134A 460 Ford V8 natural gas , Green, , , PROBLEMS: radiator and water pump have been replaced, includes stand-by battery charge, requires disconnection and removal>, As is, Where is	404 Hrs	CS60808049	CS	M-479 2006-138
	4,177.77 X-808	Grader 1954 Champion D562-B 14Ft Blade 3-71 Detroit 3 Cylinder diesel standard , Yellow, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: body exterior poor, paint poor, interior poor, lights poor , As is, Where is	Unknow n	58-562-B-61-553	CS	M-030 2006-131
	10,955.00 X-809	Tractor 1980 International Hydro 186 D436 80 HP inline 6 Cyl diesel hydrostatic , Red, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: includes loader - in good shape, Dual PTO. Radio antenna broken>, As is, Where is	4,752 Hrs	2690015U11601	CS	M-020 2006-136

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
5,600.00 X-810	Tractor 1986 John Deere 1050 Yanmer 33HP 3 Cyl inline diesel 4 Speed Hi-Lo Range , Green, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: 2 spare rear tires Turf type -Good Shape. 1 Spare front tire and rim 50% tread, box rusty>, As is, Where is	2,443	CH1050S017860	CS	M-028	2006-137
95.00 X-629	3 point Hitch Arms Fits a John Deere 425 tractor , , , , , Good			CS Prop Man	M-082	2004-091
128.00 X-630	Acetylene Torch Hoses, Torch and regulators along with the cart Tanks not included , , , , , Good			CS Prop Man	M-167	2004-091
138.00 X-795	Air Compressor Devilbiss Canada Type UDO-5004, 1963 Model 230 3 phase, 3 H.P. 208/220/440 volt 1725 RPM , , , , , Good			CS Prop Man	M-487	2006-132
118.00 X-762	Air Compressor Devilbiss, 1969 model, HUBJ-5550 Cast Iron Horizontal 80 gallon 1/2 hp 208-230/440 volt 3 phase motors, single cylinder pumps, horizontal 80 gallon , , , , , Good			CS Prop Man	M-446	2006-116
1,100.00 X-796	Air Compressor Ingersol Rand U25H Rotary Screw, 25H.P. 230/460 volt 3 phase 3530 RPM, control box , , , , , Good			CS Prop Man	M-488	2006-132
151.00 X-763	Air Dryer Sullair New Aug 2012 115 volt single phase 3.7 amp Refrigerant 134A , , , , , Good		SRS10=02250169-521 Italy	CS Prop Man	M-447	2006-116
42.00 X-764	Angle Grinder Makita 5" , 120 volt, 11000 rpm, , , , , , Good		GA5010	CS Prop Man	M-469	2006-116
287.00 X-631	Arc Welder Acklands N-250 ac/dc/p 200/230/460 60 hz single phase 78/68/34 amps 30 ft power cord , , , , , Good		JF847339	CS Prop Man	M-160	2004-091
71.00 X-632	Leaf Blower ECHO, Backpack model 2 cycle gas , , , , , Fair		PB4500	CS Prop Man	M-051	2004-091
399.99 X-633	Bandsaw Trademaster 1995 model Metal cutting, spare blade Capacity 4" x 6" mounted on a steel frame with castor wheels for easy use , , , , , Good			CS Prop Man	M-151	2004-091
752.00 X-634	Band Saw Model 180 Roubax Precision mfg. ltd. Baxter saw 3/4 hp 120 volt very good shape with spare blades , , , , , Good			CS Prop Man	M-152	2004-091
121.90 X-635	Barrel Pump Ultrapro hand pump Barrel mounted, was used with varsol (like new and clean) , , , , , Good		No. 79289	CS Prop Man	M-373	2004-091

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
110.00 X-636	Bench Grinder Baldor, W880 Buffer 1/2 hp 115/230 volt, 3600 rpm, 1 phase, 6" wheels , , , , , Good			CS Prop Man	M-432	2004-091
46.00 X-637	Bench Grinder Thor 1/3 hp 120 volt 6" wheels with wall bracket , , , , , Good		5569/7371	CS Prop Man	M-165	2004-091
127.88 X-638	Bench Vise Record No. 3 Swivel base Made in England , , , , , Good			CS Prop Man	M-406	2004-091
252.88 X-639	Bench Vise Record No.6 No swivel base, Good straight clean vise, Made in England , , , , , Good			CS Prop Man	M-431	2004-091
5.00 X-640	Fan Airworks box style, 3 speeds 18" good used fan , , , , , Good		20BA	CS Prop Man	M-438	2004-091
5.00 X-765	Fan Lasko box style 18", 3 speeds, 120 volt, good used fan , , , , , Good		3723-WMC	CS Prop Man	M-460	2006-116
32.00 X-766	Cabinet Metal specialty, lockable, 35" wide, 18" deep, 42" tall, 3 adjustable shelves , , , , , Good			CS Prop Man	M-467	2006-116
32.00 X-767	Cabinet Metal specialty, lockable, 35" wide, 20" deep, 42" tall, 3 adjustable shelves , , , , , Good			CS Prop Man	M-466	2006-116
No Bid X-641	Cabinet Trolley Cabinet on swivel castors, easy moving 3 drawer, lockable, 26" wide, 20" deep, 41" tall , , , , , Good			CS Prop Man	M-414	2004-091
33.33 X-642	Cart Home built 3 ft x 7 ft deck 3 tube tires for easy manuverability , , , , Fair			CS Prop Man	M-068	2004-091
11.53 X-643	Cart Dolly Wood handles reinforced with steel Steel wheels, good solid dolly , , , , , Fair			CS Prop Man	M-404	2004-091
No Bid X-644	Ceiling Fans Lot of 5 Canarm 48" diameters Good used fans without the speed control , , , , , Good			CS Prop Man	M-383	2004-091
20.00 X-645	Ceiling Fans Lot of 4 Canarm Pleasantaire 3 blade x 48" , , , , , Good		CP-48	CS Prop Man	M-394	2004-091
20.00 X-646	Ceiling Fans Lot of 4 Canarm Pleasantaire 3 blade x 56" , , , , , Good		CP-56	CS Prop Man	M-393	2004-091
26.91 X-647	Chain Vise Ridgid Bend O Cap Bolt on to a bench or work stand Bend or clamp 1/2 " pipe , , , , , Good		B-C-2	CS Prop Man	M-430	2004-091
No Bid X-797	Chiller Climatrol Model UDD-60420-1U 3 Phase 208 Volt, Freon Removal Required , , , , , Good			CS Prop Man	M-486	2006-132



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
385.00 X-798	Chiller Model CGWA-12006-RA 2 -60 Ton Trane -Reciprocating -3 Phase 208/230 Volt, Freon Removal Required , , , , , Good			CS Prop Man	M-485	2006-132
389.00 X-799	Chiller YORK Air Cooled Liquid Chiller, Freon Removal Required , , , , , Good			CS Prop Man	M-480	2006-132
176.91 X-648	Conduit & Pipe Stand Lot of 3 Assorted electrical conduit in rigid and emt (Rack), 500 and 700 wiremold raceway (barrel) Quantaties listed with scrap pieces in 2 barrels , , , , , Good			CS Prop Man	E-0112	2004-091
6.25 X-768	Conduit Bender Benfield 1" EMT or 3/4" rigid conduit , , , , , Good			CS Prop Man	M-461	2006-116
6.25 X-769	Conduit Bender Ideal 1.25" EMT or 1" rigid conduit , , , , , Excellent		74,006	CS Prop Man	M-462	2006-116
1.00 X-770	Conduit Benders Lot of 2 Lakin Hickey For 1/2" and 3/4" rigid electrical conduit , , , , , Good			CS Prop Man	M-465	2006-116
6.02 X-649	Casters Docap (The Pasqual) 1985 Rexdale Ont. Creeper Wood frame Steel , , , , , Good		No.36	CS Prop Man	M-177	2004-091
No Bid X-650	Cupboard 3/4" plywood construction 24" deep, 48" wide, 80" tall 2-bottom drawers, 3 -adjustable shelves, solid built , , , , , Good			CS Prop Man	M-390	2004-091
No Bid X-651	Cupboard 3/4" plywood construction 24" deep, 48" wide, 80" tall 2-bottom drawers, 3 -adjustable shelves, solid built , , , , , Good			CS Prop Man	M-391	2004-091
No Bid X-652	Cupboard Plywood Const. 15 Different Compartments 26" wide, 21" deep, 34" tall , , , , , Fair			CS Prop Man	M-398	2004-091
11.07 X-653	Cupboard Plywood Const. Varnished and double doors Lockable 4-compartments 27" wide, 17" deep, 53" tall , , , , , Good			CS Prop Man	M-413	2004-091
5.15 X-654	Cupboard Wood and Particle board Const. 4 Compartment 86" long, 12" deep, 26" high , , , , , Good			CS Prop Man	M-399	2004-091
*MT X-800	Ditch Mower 1989 Schulte Model 1050 140" Single Wing Rotary Mower , , , , , Fair		1,628,007,906	CS Prop Man	M-014	2006-132
20.00 X-655	Dolly Multi-Trolley, collapsable frame Steel, new wheels , , , , , Fair		Brico Tool Co. Burnaby B.C.	CS Prop Man	M-415	2004-091
76.00 X-656	Drive Belts Various types and sizes Includes belt sizing scale , , , , , Good			CS Prop Man	M-382	2004-091



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
52.00 X-801	Dust Collector Model 24 Donaldson Co Inc. 3 Phase 208/230 Volt 7-1/2 HP 3600 RPM , , , , , Good			CS Prop Man	M-482	2006-132
222.22 X-802	Dust Collector Model 24 Donaldson Co Inc. 3 Phase 208/230/460 Volt 7-1/2 HP 3460 RPM , , , , , Fair			CS Prop Man	M-484	2006-132
No Bid X-803	Dust Collector N.R. Murphy Ltd. 3 Phase 200/400 Volt 40 HP , , , , , Fair		90,147	CS Prop Man	M-483	2006-132
2,152.00 X-804	Dust Collector N.R. Murphy Ltd. Model FBAW-15ARR(A) 3 Phase 208/230 Volt 15 HP Fan & 1/2 HP Shaker , , , , , Good		88,344	CS Prop Man	M-481	2006-132
37.00 X-657	Induction Motor Canadian General Electric 30 hp 3 phase 208 volt 1750 rpm Frame 286T good used motor , , , , , Good			CS Prop Man	E-0100	2004-091
20.00 X-771	Drill Makita Electric 13 mm drill, 120 volt, 1/2" chuck combination, hammer, variable speed , , , , , Good		N800	CS Prop Man	M-468	2006-116
10.00 X-658	Heater Philips Electric, 1500w 120v 3-Heat settings, Fan forced , , , , , Good		HL2365G	CS Prop Man	M-392	2004-091
71.00 X-659	Exhaust Fan Canarm 16", 3- blade and louvers 1/4 HP 1725 rpm 120 volt, Totally Enclosed Ball Bearing , , , , , Good			CS Prop Man	M-395	2004-091
21.00 X-660	Exhaust Fan Canarm 16", 3- blade and louvers 1/4 HP 1725 rpm 120 volt, Totally Enclosed Ball Bearing , , , , , Good			CS Prop Man	M-396	2004-091
140.00 X-661	Exhaust Fan Welding table close proximity Custom designed could be set up for any application, 120 volt , , , , , Good			CS Prop Man	M-156	2004-091
*WD X-662	Extension Cords Good used cords, various lengths 12/3, 14/3 copper SJTW, SJOOW , , , , , Good			CS Prop Man	M-372	2004-091
No Bid X-663	Fan Blades 12"- 20", 3 and 4 blades cc and ccw rotations 3/8, 1/2, 5/8 hub sizes aluminum and steel 2 new and 10 used , , , , , Good			CS Prop Man	E-0111	2004-091
15.22 X-664	Wrench Silverline For opening a fire hydrant valve and hose caps , , , , , Good			CS Prop Man	M-116	2004-091
No Bid X-665	Flaring Tool Imperial Brass Mfg. Co. 6 different common tubing sizes, made in Chicago, USA , , , , , Good			CS Prop Man	M-437	2004-091
11.07 X-666	Flashlights (Lantern) Lot of 5 Eveready 6v LED, 3-D cell type with no batteries , , , , , Good			CS Prop Man	M-433	2004-091
505.00 X-667	Floor Jack Acklands 4000 kg Made in Denmark , , , , , Good		4,000,811,543	CS Prop Man	M-144	2004-091

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
17.00 X-668	Fluid Gun Ultrapro For extraction Use to remove oil or liquids from gear boxes or differentials etc. , , , , , Good		79,011	CS Prop Man	M-441	2004-091
151.99 X-669	Fuel Tanks Westeel 300 liter, 2.6 mm steel thickness , , , , , Good			CS Prop Man	M-420	2004-091
151.99 X-670	Fuel Tanks & Pump Westeel, 2003 model year 300 liter, 2.6 mm steel thickness 1-Fillrite hand pump, 20 L/100 strokes , , , , , Good			CS Prop Man	M-418	2004-091
85.00 X-671	Grinder 8123w Baldor grinder buffer with cord and pedestal 3/4 hp 208/230/460 3 phase 3000/3600rpm , 6" wheels , , , , , Good			CS Prop Man	M-158	2004-091
No Bid X-672	Fasteners Lot of 3 Hilti Concrete pins 100 -Hilti HPS 8/60 and 40 Hilti HPS 8/30 pins , , , , , New - Unused			CS Prop Man	C-0030	2004-091
555.55 X-673	Hoist Frame Chain Block NO.171 Home built 3.5" x 1/4" square tubing, 1 ton chain hoist 6" x 2" castors, 2 Levels , inside dimensions #1- 89" wide x 72" high, #2- 89" wide x 96" high , , , , , Good			CS Prop Man	M-425	2004-091
275.00 X-674	Hydraulic Press Nike hydraulics 20 ton steel press , , , , , Good			CS Prop Man	M-162	2004-091
35.00 X-675	Lawn Mower Husqvarna 560H combi-cut rear bagger No bag, 21 inch cut Briggs OHV, motor not running , , , , , Broken Repairable			CS Prop Man	M-046	2004-091
No Bid X-676	Lockout Devices Valve handle plastic lockout devices Roll of lockout tags with the devices , , , , , Good			CS Prop Man	M-410	2004-091
2,750.00 X-677	Metal Lathe Colchester Master 2500 Rewired for 208-230 volt 3 phase, 5 H.P. (not 600 Volt). Large selection of tools and dies and accessories with storage cabinet included. , , , , , Good			CS Prop Man	M-143	2004-091
No Bid X-678	Metering Pumps Lot of 8 Liquid Metronics, and Milton Roy Chemical injection pumps Need rebuilding, parts are available , , , , , Broken Repairable			CS Prop Man	M-417	2004-091
No Bid X-772	Metering Pumps Lot of 7 Milton Roy and Prominent Brand Good working condition, chemical injection use, last used May 15/20 , , , , , Good			CS Prop Man	M-470	2006-116
452.00 X-679	Mig Welder Acklands AK-Matic 1200 200/230 volts, 46/40 amps -Tank not included Single phase 8.3 KW 60HZ , , , , , Good		JF917899	CS Prop Man	M-159	2004-091
350.00 X-680	Mig Welder Lincoln Idealarc SP-100 with cart -Tank not included 115 volt 60 hz 20 amps input , , , , , Good		9284-808	CS Prop Man	M-161	2004-091

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
3,299.00	X-681	Milling Machine Modern 1 HP, 208 volt, 3 phase. PF-45PF, a selection of tools and dies are included. , , , , , Excellent		Ser. No. 934154	CS Prop Man	M-142	2004-091
36.99	X-682	Mop Buckets Lot of 2 Rubbermaid Good used mop buckets and 4 mop handles , , , , , Fair		6,127	CS Prop Man	M-424	2004-091
805.00	X-805	Mower 1996 Land Pride 74", 3-Point Hitch, spare blades , , , , , Good		237,193	CS Prop Man	M-013	2006-132
No Bid	X-683	Nylon Rods DSM Engineering Plastic 1 inch or 25mm 1" x 40 inchs long square, one piece, also 1" x 48 inch round, three pieces , , , , , New - Unused		QC # 442516	CS Prop Man	M-179	2004-091
5.22	X-684	Parts Bin Small parts storage unit Plastic, 40 small drawers, 19" wide, 6"deep, 10" tall , , , , , Good			CS Prop Man	M-422	2004-091
11.11	X-685	Pex Pipe 1/2" Pex Pipe (blue) Total of 50 ft in 2 lengths , , , , , Good			CS Prop Man	M-265	2004-091
1.00	X-686	Pipe Cutter No. 5 Barnes cutter Large, hand operated 3-6 inch pipe, Reed Manufacturing. Erie, PA, USA , , , , , Good			CS Prop Man	PL-084	2004-091
1.00	X-687	Pipe Cutter Ridgid No. 206 Use on cast iron pipes , , , , , Good			CS Prop Man	PL-080	2004-091
25.00	X-688	Pipe Cutter Ridgid No. 4-5 Cutter for 2-4 inch pipe , , , , , Good			CS Prop Man	PL-081	2004-091
1.00	X-689	Pipe Cutter Trimo No. 3 For 1-3 inch pipe, needs a cutter wheel, Trimont Manufacturing Co. Roxbury, PA, USA , , , , , Broken Repairable			CS Prop Man	PL-082	2004-091
1.00	X-690	Pipe Reamers Lot of 2 Hand operated pipe reamers 1/8 to 3 inch pipe sizes , , , , , Fair			CS Prop Man	PI-083	2004-091
89.79	X-691	Pipe Stand Ridgid No. 450 Tristand 1/8 to 5 inch pipes , , , , , Excellent			CS Prop Man	PL-075	2004-091
121.00	X-692	Pipe Stand Ridgid No. 450 Tristand 1/8 to 5 inch pipes , , , , , Excellent			CS Prop Man	PL-076	2004-091
250.00	X-693	Pipe Threader Components for 2.5" to 6 inch pipe threading In a box with castors works with Ridgid pipe threader machines or similar. Manufactured by A.B. Jardine & Co. , , , , , Excellent			CS Prop Man	M-078	2004-091
9.00	X-694	Pipe Threader Ridgid 65 R Hand operated adjustable from 1-2inch pipe thread , , , , , Good			CS Prop Man	PL-077	2004-091

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
9.00 X-695	Pipe Threader Ridgid 65 R Hand operated adjustable from 1-2inch pipe thread , , , , , Good			CS Prop Man	PL-078	2004-091
375.00 X-696	Pipe Threader (Electric) Lot of 4 Ridgid 400-A includes cutter, reamer and oiler pail No. 318 oiler, cutter for 1/8 -2 inch pipe and reamer the same , , , , , Good			CS Prop Man	PL-039	2004-091
15.22 X-697	Pipe Wrench Ridgid 24" For close quarters use, 24 inch pipe wrench, good shape , , , , , Good			CS Prop Man	PL-128	2004-091
1.00 X-698	Pump Gear Pump with a switch and cord 1/3 hp 120 volt Use for pressure build up or fluid transfer , , , , , Good			CS Prop Man	M-409	2004-091
60.00 X-773	Raceway Bender Wiremold Brand For metal #500 or #700 wiremold electrical raceway , , , , , Good			CS Prop Man	M-464	2006-116
74.00 X-699	Roof Anchors Lot of 2 Protecta tie off roof anchors 1-person with 310 lbs rating. Use with fall arrest harness , , , , , New - Unused			CS Prop Man	M-384	2004-091
1,123.79 X-700	Rotary Tiller John Deere Model 450 3 point hitch pto driven , , , , , Good		MOO450X215708	CS Prop Man	M-081	2004-091
5.00 X-701	Router Sears Craftsman 25000 RPM Ball Bearing 120 volt 6 amps , , , , , Good			315 CS Prop Man	C-0011	2004-091
35.00 X-702	Scale 50 lbs x 2 oz or 22 kg x 50 grams Analog dial/zero adjustment knob , , , , , Good		AM5002PL	CS Prop Man	C-0058	2004-091
No Bid X-703	Cabinet Imperial Surgical 32" tall, 20" wide, 16" deep Steel/metal with drawer and lower storage , , , , , Fair			CS Prop Man	M-411	2004-091
10.99 X-704	Shelving Steel, bolt together design - Cart not included 8-angle iron legs at 75" long and 9 shelves size 18" x 36" , , , , , Good			CS Prop Man	M-388	2004-091
146.50 X-705	Shelving Lot of 4 Steel, bolt together design, Galvanized 72" tall 24" wide Complete set up for 20-25 ft, plywood sheets for 3 levels , , , , , Good			CS Prop Man	M-400	2004-091
1.00 X-706	Stepladder 6 ft Aluminum Grade Type 3 250 lbs rating, good used paint tray and foot treads , , , , , Good			506 CS Prop Man	M-376	2004-091
15.15 X-707	Stepladder Reynolds 5 ft aluminum 250 lbs rating, good used paint tray and foot treads , , , , , Good			CS Prop Man	M-377	2004-091
5.00 X-708	Step Stool Lite Prod. Ltd Fold up frame 24" household Type 3 duty rating 200 lbs , , , , , New - Unused			CS Prop Man	M-405	2004-091

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
65.00 X-774	Stepladder Aluminum 8 Ft, heavy duty, platform ladder , , , , , Good			CS Prop Man	M-476	2006-116
77.00 X-775	Stepladder Werner 6006, Bon L Fiberglass 6 Ft , Fiberglass Grade 1 Heavy Duty, 250 lbs. rating , , , , , Good			CS Prop Man	M-458	2006-116
45.00 X-776	Stepladder Werner 6008, Bon L Fiberglass 8 ft, grade 1 heavy duty, 250 lbs. rating , , , , , Good			CS Prop Man	M-459	2006-116
35.00 X-777	Stepladder Featherlite 10 Ft , 250 lbs rating, Grade 1 Aluminum , , , , , Good		4,410	CS Prop Man	M-478	2006-116
20.00 X-778	Stepladder heavy duty aluminum 6 Ft, good paint tray and foot treads, Strong ladder , , , , , Good			CS Prop Man	M-454	2006-116
1.00 X-779	Stepladder light duty aluminum 6 Ft, good paint tray and foot treads , , , , , Good			CS Prop Man	M-453	2006-116
1.00 X-780	Stepladder light Duty Aluminum 6 Ft, good Paint tray and foot treads , , , , , Good			CS Prop Man	M-477	2006-116
1.00 X-781	Stepladder light duty aluminum 6 Ft, good paint tray and foot treads, Light duty , , , , , Good			CS Prop Man	M-455	2006-116
52.00 X-782	Stepladder light duty aluminum 8 Ft, good paint tray and foot treads , , , , , Good			CS Prop Man	M-457	2006-116
1.00 X-783	Stepladder Reynolds 5 Ft , Grade 3, Light Duty aluminum Household use , , , , , Good		365	CS Prop Man	M-452	2006-116
59.97 X-709	Storage Cabinet Sandusky metal Non adjustable shelving, 66" tall, 18" deep, 36" wide, lockable , , , , , Fair			CS Prop Man	M-442	2004-091
67.98 X-710	Storage Cabinet Steel, Double Doors, Hasp Lock 20" deep, 36" wide, 72" tall with 4 adjustable shelves , , , , , Good			CS Prop Man	M-389	2004-091
No Bid X-711	Storage Shelf Plywood, unfinished 37" wide, 6" deep, 10" tall, 9 shelves , , , , , Good			CS Prop Man	M-423	2004-091
No Bid X-712	Table Wood, with one drawer Arborite top with wood legs and frame. 60" x 34" x 30" tall , , , , , Good			CS Prop Man	M-387	2004-091
313.50 X-806	Tandem Disc King Kutter 4.5 Foot -3-Point Hitch , , , , , Good			CS Prop Man	M-018	2006-132
4.50 X-713	Tool Box Beach Brand metal No tray inside, size 20" long, 9" wide, 10" high , , , , , Good			CS Prop Man	M-407	2004-091

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-714	Tool Box Keter Poly Lots of storage 18" long, 9" wide, 10" tall , , , , , Good			CS Prop Man	M-440	2004-091
No Bid	X-715	Tool Boxes Lot of 2 Home-made open style boxes 17" long, 7" wide, 4" deep. Good used tote boxes , , , , , Good			CS Prop Man	M-434	2004-091
53.00	X-784	Tool Chest International Mechanics 8 drawers, 26" wide, 14" tall, 12" deep, lockable. , , , , , Good			CS Prop Man	M-473	2006-116
11.50	X-716	Tool Pouch Kunys EL-800 Leather Good electricians pouch with extra storage pouch , , , , , Good			CS Prop Man	M-439	2004-091
No Bid	X-717	Trouble Light Proglo A-19 incandescent lamp style med. Base 25 ft cord with 3 wire receptacle on the handle , , , , , Good			CS Prop Man	M-178	2004-091
3.50	X-718	Trouble Light Marr Brand Incandescent A-19 lamp 25 ft cord , , , , , Fair			CS Prop Man	M-435	2004-091
*WD	X-719	Trouble Light Cord Reel Woodhead 927FL 1.5 amp 125 volt Compact flourescent lamp of 13 watts 2 pin, 38 ft cord , , , , , Good			CS Prop Man	M-192	2004-091
10.00	X-720	Tubing Bender Ridgid Model 408 Lever Bender For 1/2 " Copper, Brass, or Stainless Steel tubing , , , , , Good			CS Prop Man	M-436	2004-091
51.49	X-721	Water Pump SPE50 Diamond Self Priming Effluent Pump 1/2hp 115/230 volt single phase, garden hose connections , , , , , Good			CS Prop Man	M-408	2004-091
47.97	X-785	Water Pump For Jacuzzi with electric motor 1/3 hp 115 volt Single phase 3450 rpm cord attached , , , , , Good		3C-S1/B	CS Prop Man	M-451	2006-116
29.00	X-786	Water Pump Jacuzzi water pump and elec. Motor 1/3 hp 115/230 volt single phase 3450 rpm with cord attached , , , , , Good		3C-S1/B	CS Prop Man	M-449	2006-116
10.50	X-787	Water Pump Myers Ejecto HJ33S 1/3 hp 115 volt single phase 3450 rpm , , , , , Good			CS Prop Man	M-450	2006-116
37.00	X-722	Welding and Brazing Rods Lot of 2 Various types for various needs Some for stainless steel and aluminum , , , , , Good			CS Prop Man	M-168	2004-091
356.00	X-723	Welding Table Extra heavy duty welding table custom built 49" wide, 96" long, 36" tall with 3/4" steel top and vice , , , , , Excellent			CS Prop Man	M-157	2004-091
1.00	X-724	Wheel Barrow Steel tub and handles Tube tire , , , , , Fair			CS Prop Man	M-378	2004-091
6.10	X-725	Wheel Barrow Steel tub and wooden handles Tube tire , , , , , Fair			CS Prop Man	M-379	2004-091

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
15.55 X-726	Wheel Barrow Steel tub and wooden handles tube tire , , , , , Fair			CS Prop Man	M-380	2004-091
7.00 X-727	Door Masonite 1.5 HR rating heavy wood Mohawk Flush Doors Ltd. 84" x 43" x 1.75" thick, it has a safety glass window. , , , , , New - Unused		WH1-016434	CS Prop Man	M-401	2004-091
No Bid X-728	Work Bench Plumber/pipefitter work bench 2- chain vises, 1-leg vise, 88" long, 30" wide, 38" tall , , , , , Good			CS Prop Man	M-429	2004-091
10.00 X-729	Work Table Home built steel frame and plank top 8 ft long, 3 ft wide, 3 ft tall Good strong table , , , , , Good			CS Prop Man	M-428	2004-091
356.00 X-730	Work Table Solid strong made 1/8" steel clad top 2 levels with vice Size 44" wide, 138" long, 37" tall . Tough and strong , , , , , Good			CS Prop Man	M-050	2004-091
327.89 X-731	Work Table & Vise Strong and solid built, 2 levels, 1/8" metal clad top Size 60" long, 44" wide, 36" tall, vice and magnify light included , , , , , Good			CS Prop Man	M-175	2004-091
150.00 X-732	Work Table & Vise Wooden, sheet metal top, Vice attached 3 -elec. outlets and cord, size 36" wide, 96" long, 36" tall, 2 levels and strong made , , , , , Good			CS Prop Man	M-176	2004-091
No Bid X-733	Bulletin Board 96" x 48" good fabric covered board Aluminum frame, Beige color , , , , , Good			CS Prop Man	M-419	2004-091
40.00 X-734	Video Screen Luma projection screen 70" x 70" with wall mounting brackets, made in Draper, Indiana, USA , , , , , Good			CS Prop Man	M-426	2004-091
12.00 X-735	White Boards Lot of 3 Quartet dry erase 18" x 24" aluminum, 2 used, 1 new , , , , , Good			CS Prop Man	M-416	2004-091
2,528.00 X-811	Truck 1989 Chev 30/3500 Dump box 1 ton frame 5.7 Litre V8 Gas standard 4 speed Dual Rear Axle, White & Green , TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Dump box fair shape, box cross rails poor, rear doors bent somewhat, roll tarp working, PTO cable needs adjusting. trailer hitch good>, As is, Where is	104,522 Kms	1GBHR34K5KJ113384	CVA	801554\ M-034 TOW ONLY, No SGI Inspection.	2006-134



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
4,995.00 X-812	Truck 1990 Chev 30/3500 Telelift Ladder, 2WD 5.7 Litre V8 Gas standard 4 speed Dual Rear Axle, White, TOW ONLY, No SGI Inspection. It is unknown if any repairs or safety concerns exist (if any). Requires a passed SGI Inspection to be licensed. Buyer assumes full responsibility for repairs if required. , , PROBLEMS: Passenger door requires repair, body is rusty. Engine uses oil and somewhat hard on gas. fuel tank solenoid not working for dual tanks, lift was certified 2 years ago>, As is, Where is	225,688 Kms	1GBHC34KXLE214836	CVA	801553\ M-033 TOW ONLY, No SGI Inspection.	2006-135
<b>PRINCE ALBERT, Sask Liquor &amp; Gaming, 99-9th St E.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Darcy Huyghebaert 306-787-9226</b>						
160.00 X-576	Pallet Jack 2010, Raymond, 102T-F45L Built-in charger not working. Maximum Capacity 4500lbs. 1409 Hrs on it. Unit works but will not charge with attached charger , , , , Broken Repairable		102-10-16254	SLGA	1	2004-040



Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>REGINA, CS Property Management, 1660 Park Street.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Rhonda Gelowicz 306-552-8049, or at rhonda.gelowicz@gov.sk.ca</b>						
<b>500.00</b>	<b>X-508</b>	Key Cutting Equipment Contents of lock shop from Valley View Centre Generator, code cutting machine, re-keying kits, blank keys. Old and new hardware; lever locks, knobs, mortise locks, etc. NO VIEWING Available. All items have been boxed - Please review pictures ONLY. , , , , ,			CS Prop Man	1 IMG_0385- 2003-1198 IMG_0394
<b>REGINA, Energy and Resources, 201 Dewdney Ave E.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Richard Wood 306-787-2621, richard.wood.@gov.sk.ca</b>						
<b>32.00</b>	<b>X-580</b>	Axes Lot of 16 26"-34" shafts , , , , , Fair			ER	25 2004-079
<b>13.05</b>	<b>X-581</b>	Benches Lot of 2 Wood 1'x9' bench sits 18 3/4" high, legs screw into place and are stored within the frame of the bench. The benches could use a coat of paint. , , , , , Good			ER	11 2004-079
<b>21.51</b>	<b>X-582</b>	Bow Saws Lot of 12 24"-48" blades, some rust on blade , , , , , Fair			ER	23 2004-079
<b>16.51</b>	<b>X-583</b>	Bow Saws Lot of 7 30" & 42" blades , , , , , Good			ER	24 2004-079
<b>35.22</b>	<b>X-584</b>	Buckets Lot of 17 Metal 12 3/4" diameter, round , , , , , Fair			ER	27 2004-079
<b>25.22</b>	<b>X-585</b>	Buckets Lot of 5 Metal 20 1/2" x 20 1/2", square and round , , , , , Fair			ER	26 2004-079
<b>258.00</b>	<b>X-586</b>	Generator Honda, E 300, 1/1/1973 works well, runs, few bolts missing on house surrounding , , , , , Good		2,108,070	ER	28 2004-079
<b>235.00</b>	<b>X-587</b>	Generators Lot of 2 Honda, EG 1400X works well, runs, starts to leak after it's turned off if gas is still on , , , , , Good		GX110-1230661, GX110-1513465	ER	29 2004-079
<b>326.00</b>	<b>X-588</b>	Generators Lot of 2 Honda, EG 1400X 08/09 starts and runs good , , , , , Good		GX110-1686838, CX110-1557927	ER	30 2004-079
<b>345.00</b>	<b>X-589</b>	Generators Lot of 2 Honda, EM 2500 12/13 starts and runs good, slight leak if fuel isn't turned off after it runs , , , , , Good		GC02-3453655, 1068738	ER	31 2004-079

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
	385.00 X-590	Outboard Motor Evinrude 15HP 2-stroke engine, comes with jerry can and fuel hose , , , , , Fair		G 04085302	ER	19	2004-079
	413.00 X-591	Outboard Motor Evinrude 15HP 2-stroke engine, comes with jerry can and fuel hose , , , , , Fair		G04085264	ER	20	2004-079
	468.00 X-592	Outboard Motor Johnson 15HP 2-stroke engine, comes with jerry can and fuel hose , , , , , Fair		C 8244106	ER	12	2004-079
*MT	X-593	Outboard Motor Johnson 20HP 2-stroke engine, comes with jerry can and fuel hose , , , , , Fair		R 08172662	ER	16	2004-079
	287.00 X-594	Outboard Motor Johnson 15HP 2 stroke engine, comes with jerry can and fuel hose, missing the lower unit (gearbox) , , , , , Broken Repairable		G 04486035	ER	15	2004-079
	320.00 X-595	Outboard Motor Johnson 15HP 2-Stroke engine, comes with jerry can and fuel hose, engine needs a new pull cord , , , , , Broken Repairable		C 8244073	ER	13	2004-079
	180.00 X-596	Outboard Motor Johnson 15HP 2-stroke engine, comes with jerry can and fuel hose, leaks oil , , , , , Broken Repairable		G 03074985	ER	14	2004-079
	329.00 X-597	Outboard Motor Mercury 9.8HP 2-stroke engine, comes with jerry can and fuel house , , , , , Fair		A 700539	ER	17	2004-079
	513.00 X-598	Outboard Motor Mercury 8HP 2-stroke engine, comes with jerry can and fuel hose , , , , , Fair		OA740199	ER	18	2004-079
No Bid	X-599	Propane Fridge Unique doesn't cool , , , , , Broken Repairable			ER	21	2004-079
No Bid	X-600	Propane Fridge won't ignite , , , , , Broken Repairable			ER	22	2004-079
	556.00 X-601	Prospect Tent Lot of 5 Manta 12'x14'x7', white, needs repair, poles not included, zipper torn , , , , , Fair			ER	9	2004-079
	5.01 X-602	Satellite Finders + Cables Egel Aspen, SF-99 950-2250 9 satellite finders (one with back missing) that varying in condition and 8 coaxial cable (one with broken end) , , , , , Good			ER	41	2004-079
No Bid	X-603	Satellite System Raven satellite dish, modern charger, 2 single coaxial cables and 1 satellite finder, small coaxial cable. , , , , , Poor			ER	40	2004-079

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
No Bid	X-604	Satellite System Raven Satellite system is mostly complete but is missing the limb and the bracket that attach the satellite dish to its support. Does not come with a router. , , , , Fair		UE088-34365-W	ER	39	2004-079
No Bid	X-605	Satellite System Raven Satellite system is mostly complete. Only missing parts are the limb that attaches from the satellite dish to the bracket support and phone. The router is not included. , , , , Good		UA076-01109-G	ER	38	2004-079
31.00	X-606	Tarp Lot of 6 Canvas Fly 12'x9', dirty, minor damage , , , , Fair			ER	8	2004-079
1.25	X-607	Tent Fly Canvas Fly 11'x12', one large hole, two smaller holes, no rope , , , , Poor			ER	5	2004-079
46.00	X-608	Tent Fly Lot of 5 Canvas Fly 12'x14', minor damage, some missing ropes , , , , Fair			ER	3	2004-079
15.00	X-609	Tent Fly Lot of 2 Canvas Fly 12'x9', needs repair, missing ropes , , , , Fair			ER	7	2004-079
37.00	X-610	Tent Fly Lot of 3 Canvas Fly 15'x18', minor damage , , , , Fair			ER	6	2004-079
40.00	X-611	Tent Fly Lot of 19 Canvas Fly 18'x20', minor damage , , , , Fair			ER	4	2004-079
256.00	X-612	Tents Lot of 2 External Frame Protector Tent 12'x14'x10', canvas walls, no floor, 2 screen windows, chimney hole with velcro cover flap, includes centre steel pole, needs cleaning, some holes, needs some repair and poles for walls or something to tie it to , , , , Fair			ER	2	2004-079
130.00	X-613	Tents Lot of 4 Holiday Tent 10'x8'x6', cotton canvas walls, tarp floor (100% polyethylene), aluminum poles, minor damage, repairable, most legs included, no pegs , , , , Fair			ER	1	2004-079
5.75	X-614	Tents Lot of 3 Woods Renevous Holiday Tent 8'x6'x6'x8'x11', canvas tent, a few small holes need patches, missing poles, no pegs , , , , Fair			ER	10	2004-079
278.90	X-615	Watercraft 93' Achillies, SEM-93-0015 14 ft, a couple of patches on the underside of the boat that are not very sealed. Missing a round bolt on the rowing attachment. Boards are good but don't come with paddles or a bag. , , , , Fair		ACH008851293	ER	35	2004-079

	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>WD</b>	<b>25.00 X-616</b>	Watercraft 93' Achillies, SEM-93-0016 14 ft, the top of the boat is in good shape but the underside is really rough. The boat does hold air. The boards are in good shape and there are 1 1/2 paddles. There is a big bag for the boards/paddles but none for the boat. , , , , , Poor		ACH008521293	ER	32	2004-079
	<b>456.72 X-617</b>	Watercraft Zodiac, SIR-02-0032 short shaft transom, 1/1/2002 Transom is slightly rotted and has few patches on the keel. Overall, not a bad boat, highly fixable. , , , , , Fair		XDCB372BI102	ER	37	2004-079
	<b>370.00 X-618</b>	Watercraft Zodiac, SIR-02-0035 short shaft transom, 1/1/2002 14 ft, boat holds air. The bottom is in fairly rough shape with lots of patches that may or may not be water tight. The boards and side rails are in good shape. , , , , , Fair		XDCB379BI102	ER	34	2004-079
	<b>250.00 X-619</b>	Watercraft Zodiac, SIR-06-0033A Short shaft, 1/1/2006 14 ft, boat is moldy and the transom has slightly rotted. The boards are in rough shape, especially the wooden parts. The bottom of the boat is in very bad shape with countless patches. , , , , , Poor		XDCB202MI506	ER	36	2004-079
	<b>370.00 X-620</b>	Watercraft Zodiac, SIR-02-0034 Short shaft transom, 1/1/2002 14 ft, boat has a small leak in it portside. The bottom is in fairly rough shape with lots of patches that may or may not be water tight. The boards and side rails are in good shape. , , , , , Fair		XDLB912BA202	ER	33	2004-079
<b>REGINA, Finance, 2350 Albert Street.</b>							
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Lisa Molleken 306 787-9721, lisa.molleken@gov.sk.ca</b>							
	<b>8.00 X-753</b>	File Cabinets Lot of 5 Vertical, 4 Drawer, Metal 18" d 28" 51" h. Picture shows 4 filing cabinets, there are 5 available. Unknown if lockable or if there are keys. , , , , , Good			FIN	CDP 29340 4	2003-1214
	<b>127.51 X-754</b>	Shelving Lot of 27 units Metal (for library) Approx. 7 shelves per unit including top and bottom, Half-back Shelving Units 37"X 9"X 84 , , , , , Good			FIN	CDP 29355 2	2003-1214
	<b>286.99 X-755</b>	Shelving Lot of 10 Units Metal, clip style Approx. 7 shelves per unit including top and bottom, Open -back Shelving Units 36 x 14.75 x 76 , , , , , Good			FIN	CDP 29348 3	2003-1214
	<b>No Bid X-756</b>	Table Metal Frame Laminate Top, 60"x30"x29 , , , , , Fair			FIN	CDP 29339 1	2003-1214

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>REGINA, Highways, 1610 Park Street</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Ed Hildebrand 306-694-3881, 306-533-3421, or at ed.hildebrand@gov.sk.ca</b>						
88.50	X-751			HI	1 pic 49-1-1 49-1-2	2004-089
	Sign Posts Lot of Approx. 49 Broken ends, Fir Wood 4x6 8' to 14' Banded in bundle as pictured, Must have flatdeck trailer for pick up. Used. , , , , Fair					
91.50	X-752			HI	2 pic 56-2-1 56-2-2	2004-089
	Sign Posts Lot of Approx. 56 Broken Ends, Fir Wood 4x6 8' to 14' Banded in bundle as pictured, must have flatdeck trailer for pick up. Used. , , , , Fair					
<b>REGINA, Sask Liquor &amp; Gaming, , SLGA Distribution Center: GTH, 12252 Ewing Avenue.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Allen 306-787-4286, or Darcy Huyghebaert 306-787-9226, dhuyghebaert@slga.gov.sk.ca</b>						
60.00	X-577		102-13-28592	SLGA	1	2004-041
	Pallet Jack 2013, Raymond, 102T-F45L Batteries are no good, machine has electrical issues, parts only , , , , Beyond Repair					
No Bid	X-505			LRWS	Lot 29309	2002-1194
	Chair Plastic Frame 5 castors, no arms, brown fabric , , , , Poor					
No Bid	X-506			LRWS	Lot 29307 Lot 29308	2002-1194
	Chairs Lot of 2 Metal Frame Metal frame, no wheels, arm rests, red fabric and grey fabric , , , , Poor					
No Bid	X-507			LRWS	Lot 29310	2002-1194
	Table Pepperdust Metal frame, 60"X30"X30 Items on the table not included , , , , Fair					
<b>SASKATOON, Sask Liquor &amp; Gaming, 200 Confederation Dr. Confederation Park Mall.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Wanda 306-933-5315, or Darcy Huyghebaert 306-787-9226, dhuyghebaert@slga.gov.sk.ca</b>						
240.00	X-578		102-09-13402	SLGA	1 SLGA	2004-042
	Pallet Jack 2009, Raymond ,102T-F45L Built in charger , Max capacity 4500lbs, 1806 Hrs on it , , , , Good					

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>SASKATOON, Sask Liquor &amp; Gaming, 503 Nelson Road, University Heights.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Irene 306-933-5317, Darcy Huyghebaert 306-787-9226, dhuyghebaert@slga.gov.sk.ca</b>						
<b>431.00</b>	<b>X-579</b>	Floor Scrubber & charger Nobles Speed Scrub 2001HD, 612086 Floor scrubber, purchased in 2005, with separate charger , operational , , , , , Good		612086-10249392	SLGA	1 SLGA 2004-043
<b>WADENA, Environment, 77 1st Street NE.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Dale Achtymichuk 3016-338-6255, dale.achtymichuk@gov.sk.ca, or Scott Harvey 306-338-6257, scott.harvey@gov.sk.ca</b>						
<b>51.51</b>	<b>X-514</b>	Safe Gardex Combination Safe, Steel Outside dimensions: 18.5"Lx18.5"Wx24"H Combination will be provided to Success Bidder. , , , , , Fair		62,111 ENV	1	2004-001
<b>WEYBURN, Environmnet, 201 - 110 Souris Ave.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Lindsey Leko 306-891-9106 or at Lindsey.Leko@gov.sk.ca</b>						
<b>503.00</b>	<b>X-628</b>	Snowmobile 1998 Polaris Touring Trail, Model 099ET4ESA Non-Operational, broken cowling hinges. , , , , , Poor		4XAET4ES0XC069026	ENV	1 26 2004-092
<b>WEYBURN, Highways, 18 Souris Avenue (W).</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact shannon Mack 306-848-2436, shannon.mack@gov.sk.ca or Patricia Butz at patricia.butz@gov.sk.ca</b>						
<b>No Bid</b>	<b>X-623</b>	Printer Cartridge HP Laser Jet 27X , , , , , New - Unused			HI	Pic #3 1911-950
<b>No Bid</b>	<b>X-624</b>	Printer Cartridge Lot of 2 HP Laser Jet 42A & 42X , , , , , New - Unused			HI	Pic #4 1911-950
<b>No Bid</b>	<b>X-625</b>	Printer Cartridge Lot of 4 HP Laser Jet 501A & 503A , , , , , New - Unused			HI	Pic #1 1911-950
<b>No Bid</b>	<b>X-626</b>	Printer Cartridge Lot of 2 HP Laser Jet 92A , , , , , New - Unused			HI	Pic #5 1911-950
<b>No Bid</b>	<b>X-627</b>	Printer Cartridge HP Laser Jet Q6470A , , , , , New - Unused			HI	Pic #6 1911-950
<b>No Bid</b>	<b>X-621</b>	Printer Cartridge Lot of 3 Canon 131 , , , , , New - Unused			HI	Pic #2 1911-950

No Bid	Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
	X-622	Printer Cartridge HP Laser Jet 05A , , , , , New - Unused			HI	Pic #7	1911-950
<b>WOLLASTON LAKE, ENV, Block 1 Lot 10.</b>							
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Warner Carlson -306-758-6254, warner.carlson@gov.sk.ca, or Troy Hilts 306-688-8812, troy.hilts@gov.sk.ca</b>							
	150.00 * 11-502	Mobile Home Older model bunk trailer, metal/wood construction Trailer is on wheels and has a hitch. 10' wide by 47' long. Condition: outside is fair with some broken windows, roof is fair and does not leak, inside is fair but will likely require flooring. Tires appear to be fair. Utilities are all disconnected except some plumbing will need to be disconnected/moved before removal. Includes wooden addition on side, approx. 20' x 8'. Condition: in poor shape, metal roof, broken window between addition and trailer. Includes washer, dryer, fridge and stove. All appliances were new when trailer was moved in 2015. Furniture included is in fair condition. Also includes Propane Furnace. Buyer is responsible for site cleanup, removal of blocking, skirting and any other material from trailer or addition. Buyer is required to agree to a site License Agreement. (attached) , , , , , Fair		1763733 SK5715	ENV	1	1909-606
<b>YORKTON, White Spruce, Central Services, Property Management, NE-35-TP26-R5-W2ND.</b>							
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Mark Bigoraj 306-786-5871, mark.bigoraj2@gov.sk.ca</b>							
No Bid	X-515	Unit Heater Flame-Master, Model: EM-135-HFP 135,00 BTU, Natural-gas Operational , , , , , Fair			13,019	CS Prop Man	2 Unit heater 21-a & 21-b 2003-1226
No Bid	X-516	Unit Heater Olson, Model: KAS-100-E 80,000 BTU, Natural-gas Operational , , , , , Fair		03754KAGN		CS Prop Man	1 Unit heater 20-a & 20-b 2003-1226
No Bid	X-517	Unit Heater Olson, Model: KAS-200-E 160,000 BTU, Natural-gas Operational , , , , , Fair		24743KAUN		CS Prop Man	3 Unit heater 23-a & 23-b 2003-1226
No Bid	X-518	Unit Heater Olson, Model: KAS-200-E 160,000 BTU, Natural-gas Operational , , , , , Fair		24756KAUN		CS Prop Man	4 Unit heater 24-a & 24-b 2003-1226
No Bid	X-519	Water Cooler Haws, Model: HF8 115 volt Operational , , , , , Fair			20,839	CS Prop Man	5 Water Fountain 1,2 2003-1226

Item #	Description	Kms	Serial Number	Ministry	Ministry /	Disposal
<b>WEYBURN, Highways, 18 Souris ave.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Tyson Eddy 306-848-2442 or at tyson.eddy@gov.sk.ca</b>						
1,360.00	X-792		Trailer 2012 Aluma MC210 14" tires, 78"x 138" deckcracks on frame , , , , , , Poor	1YGUS1215CB079280	HI	M-4436 2006-115
<b>YORKTON, Highways, 245 York Road East.</b>						
<b>Due to COVID-19, ON-LINE VIEWING ONLY. NO ON-SITE VIEWING. For information on items contact Brian Perih, 306-786-1651, 306-621-7379, or at brian.perih@gov.sk.ca, or Ed Patzwald 306-786-1687, 306-620-5741, or at ed.patzwald@gov.sk.ca</b>						
376.00	X-502		Posts Lot of 75 to 100 Wooden, mostly fir. approx. 4" x 6" x 14', old, broken sign posts. Approximate weight of lift is 6500 lbs; must bring flat deck trailer for assistance with loading. If flat deck trailer cannot be provided, loading is responsibility of buyer. , , , , , Fair	NA	HI	1 2003-1213